



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**



No. F6/DFS/MS/NDZ/2026/470

Dated: -17/03/2026

To,

Sh. Gulshan Dhingra,  
Under Secretary (Establishment),  
A-Wing, Room No. 4017,  
JNB, 23-D, Janpath,  
New Delhi - 110011

**Sub: Regarding request for deploying a Technical Expert at Jawaharlal Nehru Bhawan, Ministry of External Affairs, New Delhi.**

Sir,

Please refer your email dated 12.02.2026 and the enclosed letter No. Q/OA/551/03/2021 dated 12/02/2026 on the subject cited above.

In this connection, this is to inform you that the Delhi Fire Service functions under the provisions of the Delhi Fire Service Act, 2007 and the Rules made thereunder. It is pertinent to mention that the Delhi Fire Service does not provide consultancy services, supervision of work, or certification of rectification during the execution stage of any work.

However, you may apply for a re-inspection of the premises upon the completion of the shortcomings issued vide letter No. F.6/DFS/MS/NDZ/2025/54 dated 06/02/2025 (copy enclosed). Further, Rule 38 of the Delhi Fire Service Rules, 2010 (copy enclosed) casts an obligation and liability on the occupier of the building/premises to maintain the fire safety measures installed therein.

Yours faithfully,

Encl: - As Above

(Dr. S. K. Tomar)

Dy. Chief Fire Officer  
Delhi Fire Service

Copy to: -

1. The Chairman, NDMC, Palika Kendra, New Delhi.

C/34

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001**

No.F.6/DFS/MS/NDZ/2025/ 54

Dated: 06/02/2025

To,

Sh. Pradeep Kumar Mishra,  
Administrative Officer (OA),  
Ministry of External Affairs,  
New Delhi.

**Sub:** - Regarding of fire safety certificate in r/o Jawahar Lal Nehru Bhawan, New Delhi.

Sir,

This has a reference to mail id <aoestt@mea.gov.in> dated 06.01.2025, on the subject cited above. In this connection, it is to inform you that the premise was inspected by the officers concerned of this department on 24/01/25 in the presence of Sh. Sandeep and observed that the following shortcomings

1. Fire check door glass found broken in basement and door closers found removed at some places.
2. Pressurization of staircases & lift shaft found nonfunctional and not integrated with fire detection system.
3. Electric shaft are not sealed.
4. Smoke management system in basement found nonfunctional and also not integrated with detection system.
5. In basement sprinkler are hidden above ventilation shaft, required to be lowered below ducting.
6. Exit Signage found inadequate in basement.
7. Diesel Engine pump found nonfunctional.
8. Further, temporary rooms /partitions have been made in basement and firefighting system such as detection system , sprinklers is not extended to that area and use of some portion of basement has been changed to residential ( barrack ) , Accordingly approval from NDMC is required.

In view of above case is rejected with a request to rectify the above shortcomings at the earliest for further consideration in the matter.

Yours faithfully

(Atul Garg)  
DIRECTOR  
Delhi Fire Service

Copy to:

1. The Chairman, NDMC, Palika Kendra, New Delhi.