GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO.F6/DFS/MS/SZ/2025/ 1869 Dated: 21/10/2025

To,

Sh. Neeraj Vacher (Asstt. GM)
NABARD- 24,
07, Rajendra Place, New Delhi-110008.

Subject: -Regarding renewal of Fire Safety Certificate in r/o NABARD- 24, Rajendra Place, New Delhi- 110008.

Sir,

This is in reference to your letter No. NB.ND/Fire Safety/89019/2025-26, dated 17.09.2025 on the subject cited above. In this connection it is to inform you that the above said premises have been inspected by the officers concerned of department on dated 13.10.2025 in presence of the Manager, to check the status of the shortcomings issued by this department vide letter No. F.6/DFS/MS/2025/165 dated 16.04.2025. During the course of inspection, it was observed that the shortcomings are not complied.

In view of the above 'Fire Safety Certificate' cannot be renewed at this stage. You are requested to rectify the above shortcomings under intimation to this department for taking further necessary action in this matter, otherwise action will be initiated against the said building premises as per Delhi Fire Service Act 2007, Rules 2010.

Yours faithfully

(A.K. Malik)
Dy. Chief Fire Officer
South zone

Copy to: -

1. The Commissioner, MCD, Civic Centre, Minto Road, New Delhi.

C/55

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F.6/DFS/MS/2025/ 165 Dated 16/04/2025

To,

Sh. Upma Saxena,
Deputy General Manager,
NABARD, 24, Rajindra Place, New Delhi.

Sub:- Regarding renewal of FSC in r/o NABARD, 24, Rajindra Place, New Delhi.

Sir,

This has reference to your letter no. NB.ND/Fire Safety/156422/2024-25 dated 04.03.2025, on the subject cited above. In this connection it is to inform that the site was visited by the officers concerned of this department on 03/04/2025 in the presence of Sh. Manish Gupta, and the following shortcomings were observed:-

1. Fire checks door found removed with normal door at 7th floor.
2. Electrical shaft required to be sealed properly.
3. Detectors found nonfunctional at some office.
4. Smoke management system found non functional in basement and also not integrated with alarm system .

In view of above case is rejected with a request to rectify the above shortcomings at the earliest for further consideration in the matter. Further, the occupancy of the building/premises in absence of requisite fire safety arrangements shall be at risk and liability of owner/occupier. The licensing /statuary authority may take suitable necessary action as deemed fit.

Yours faithfully

15.4.2025

(Virendra Singh)
Chief Fire Officer
Delhi Fire Service