



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



Application ID. 52026031201595

Dated: 02-06-2026

SHORTCOMING(S)

With reference to your application ID **52026031201595** dated **02-06-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Amba Tower** at **Plot No-2, Community Centre, DC Chowk, Sec-9, Rohini, Delhi-110085**. from fire safety point of view in presence of **Sh. Prashant Sagar** on dated **26/05/2026** During the course of inspection following observations were made:-

1. FCD found removed at some places.
2. Smoke ventilation system found removed in basement and upper floors corridor.
3. Hose reel hose is provided but not functional.
4. Smoke detector system is provided but not functional.
5. Sprinklers system is provided but not functional.
6. Internal hydrant is provided but not functional.
7. Yard hydrant is provided but not functional.
8. The pump room found locked and inspection couldn't be carrying out.
9. Exits signs found removed.
10. Refuse area covered by individual unit owner/occupier needs to be proper clear in case of emergency.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

S.K.DUA
Chief Fire Officer

Copy to:-

1. Prashant Sagar , B-209, 2nd Floor, Ekta Apartment, Rohini, Sector-13, PO Rohini Sector-7, 110085
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.