



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



Application ID. 52026032801902

Dated: 15-05-2026

SHORTCOMING(S)

With reference to your application ID **52026032801902** dated **15-05-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Vivekanand CGHS Ltd.** at **Plot No. 02, Sector- 05, Dwarka, New Delhi- 110075** from fire safety point of view in presence of **Mr. Sumir Gupta** on dated **08/05/2026** During the course of inspection following observations were made:-

1. Internal road of all around the building found blocked/ encroached.
2. Hose Reels provided in each block but found not functional.
3. Automatic Sprinkler System provided in basement but found not functional.
4. Internal hydrant and Yard hydrant provided but found not functional.
5. Terrace level fire pump provided as per requirement but found not functional.
6. Exit Signs found removed at some places.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

A.K.Malik
Chief Fire Officer

Copy to:-

1. SUMIR GUPTA , Plot no 2, Sector 5, DWARKA, New Delhi, 110075
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.