



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



Application ID. 52026032901918

Dated: 01-05-2026

SHORTCOMING(S)

With reference to your application ID **52026032901918** dated **01-05-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Bhandari House** at **Plot No. A-35-36, Commercial Complex, Dr. Mukharjee Nagar, Delhi-110009** from fire safety point of view in presence of **Sh. Lalit Kumar, IT Head and Sh. Dhurv Patel, Supervisor** on dated **23/04/2026** During the course of inspection following observations were made:-

- 1.Fire check door found removed.
- 2.First Aid Hose Reels found non-functional.
- 3Automatic fire detection and alarming system found non-functional.
- 4.MOEFA found non-functional.
- 5.PA system found removed.
- 6Automatic sprinkler system found non-functional.
- 7.Internal hydrates found non-functional.
- 8.Fire pump found non-functional.
- 9.The overhead water storage tank of 15,000 liters capacity is inadequate against the required capacity of 50,000 liters.
- 10.Exit signages found removed.
- 11.Standby power supply found non-functional.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

S.K.DUA
Chief Fire Officer

Copy to:-

1. Bimla Kumari , S-444, D-School, Shakurpur, Delhi, 110092
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.