



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



Application ID. 52026060203331

Dated: 08-09-2026

SHORTCOMING(S)

With reference to your application ID **52026060203331** dated **08-09-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Saarathi International Sr. Sec. School** at **Begumpur Extn. (Sec-37, Rohini), Near Hanuman Chowk, Begumpur, Delhi-110086** from fire safety point of view in presence of **Sh. Anil Kumar Yadav, Owner** on dated **20/07/2026** During the course of inspection following observations were made:-

- 1.02 nos. staircases in each block, A-Block and B-Block are required to be provided with the width of 1.50 m each and upto terrace floor against the 01 no. staircase provided at each block.
- 2.Smoke Management System is not provided in A-Block basement.
- 3.Overhead water storage tank of A-Block is 4,000 ltrs. and B-Block-8,000 ltrs. against the requirements of 15,000 ltrs and 10,000 ltrs. respectively

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

A.K.Malik
Chief Fire Officer

Copy to:-

1. SAARTHI INTERNATIONAL SCHOOL , KH.NO.20/18 & 20/23,, BLK-H, NAVEEN VIHAR, New Delhi, 110086
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.