



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



Application ID. 52026061503689

Dated: 23-09-2026

SHORTCOMING(S)

With reference to your application ID **52026061503689** dated **23-09-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **The Samrat Ashoka Co-op Group Housing Society Ltd.** at **Plot No. 36/2, Sector-9, Rohini, Delhi-110085** from fire safety point of view in presence of **Ms. Kamini Gupta, President** on dated **20/07/2026** During the course of inspection following observations were made:-

1. 06 m width of internal road found obstructed and reduced.
2. Sealing of electrical shafts found removed.
3. First-Aid-Hose-Reels found non-functional.
4. MOEFA found removed.
5. Fire pump of 450 LPM at terrace level found non-functional.
6. Draw-off connection and Fire service inlet found removed.
7. Exit signage found removed.

Communication in lift car found removed, firemen's grounding switch found non-functional and lift signage found removed

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

A.K.Malik
Chief Fire Officer

Copy to:-

1. KAMINI GUPTA , A-302, SAMRAT ASHOKA APTT, SECTOR-9, ROHINI, DELHI, 110085
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.