



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



Application ID. 52026070704279

Dated: 27-07-2026

SHORTCOMING(S)

With reference to your application ID **52026070704279** dated **27-07-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Mother Divine Public School (MD Memorial Charitable and Educational Society)** at **Pocket G-31, Sector-3, Rohini, Delhi-110085** from fire safety point of view in presence of **Sh. Vijay Sharma** on dated **14/07/2026** During the course of inspection following observations were made:-

- 1.06 m internal road all around the building for fire tender movement is not provided.
- 2.FCD is not provided in staircases
- 3.Provision of Lifts Shaft, lift lobby, communication in lift car is not provided.
- PA System Panel, Battery Backup and Building Floor Plans is not provided

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

Sachin Rana, IAS
Pr. Director

Copy to:-

1. Mother Divine Public School , C-2090 A FIRST FLOOR, SUSHANT LOK PHASE -1, BEHIND PEACH THREE HOTEL, GOUL SOUK GURUGRAM, 122001
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.