



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



Application ID. 52026072204627

Dated: 14-08-2026

SHORTCOMING(S)

With reference to your application ID **52026072204627** dated **14-08-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Midfields Sr. Secondary School** at **Dabur Enclave, Jaffarpur Kalan, New Delhi-110073** from fire safety point of view in presence of **Mr. Narender Kumar - Manager** on dated **04/08/2026** During the course of inspection following observations were made:-

1. Automatic Sprinkler System provided but found nonfunctional.
2. Terrace fire pump provided but found nonfunctional.
3. Overhead tank of 2000 liters capacity is provided against the requirement of 5,000 liters.
4. Exit & floors Signage's not provided in strategic location in the building.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

Sachin Rana, IAS
Pr. Director

Copy to:-

1. NARENDER KUMAR , H.NO.- 49, VPO, DHANSA, NEW DELHI, 110073
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.