



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

75
आज़ादी का
अमृत महोत्सव

No. F6/DFS/MS/ECN/2026/432

Dated: 25/09/2026

To,

Sh. Gulshan Dhingra,
Under Secretary (Establishment),
A-Wing, Room No. 4017,
JNB, 23-D, Janpath,
New Delhi - 110011

**Sub: Regarding request for deploying a Technical Expert at Jawaharlal Nehru Bhawan,
Ministry of External Affairs, New Delhi.**

Sir,

Please refer your email dated 12.08.2026 and the enclosed letter No. Q/OA/551/03/2021 dated 12/08/2026 on the subject cited above. In this connection, it is to inform you that the said building was inspected by the officers concerned of this department on 29/08/2026 in the presence of Sh. Rahul A.E. (Electrical) and observed that shortcomings conveyed vide this office letter No. F.6/DFS/MS/NDZ/2025/54 dated 06/02/2025 (copy enclosed) have been complied except the shortcoming placed at Sr. No. 1 & 8 in the said letter mentioned as: -

1. Fire Check Door glass found broken in basement and door closers found removed at some places.
2. Temporary rooms/partitions have been made in basement and firefighting system such as detection system, sprinklers are not extended to that area and use of some portion of basement has been changed to residential (Barrack). Accordingly, approval from NDMC is required.

In view of the above, you may apply for a re-inspection of the premises upon the completion of the aforementioned shortcomings. Further, the occupancy of the premises in the absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,

Encl: As Above


(Dr. S. K. Tomar)
Chief Fire Officer
Delhi Fire Service

Copy To: -

1. The Chairman, NDMC, Palika Kendra, Parliament Street, New Delhi - 110001.

C/74

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

No.F.6/DFS/MS/NDZ/2025/ 54

Dated: 06/02/2025

To,

Sh. Pradeep Kumar Mishra,
Administrative Officer (OA),
Ministry of External Affairs,
New Delhi.

Sub: - Regarding of fire safety certificate in r/o Jawahar Lal Nehru Bhawan, New Delhi.

Sir,

This has a reference to mail id <aoestt@mea.gov.in> dated 06.01.2025, on the subject cited above. In this connection, it is to inform you that the premise was inspected by the officers concerned of this department on 24/01/25 in the presence of Sh. Sandeep and observed that the following shortcomings

1. Fire check door glass found broken in basement and door closers found removed at some places.
2. Pressurization of staircases & lift shaft found nonfunctional and not integrated with fire detection system.
3. Electric shaft are not sealed.
4. Smoke management system in basement found nonfunctional and also not integrated with detection system.
5. In basement sprinkler are hidden above ventilation shaft, required to be lowered below ducting.
6. Exit Signage found inadequate in basement.
7. Diesel Engine pump found nonfunctional.
8. Further, temporary rooms /partitions have been made in basement and firefighting system such as detection system , sprinklers is not extended to that area and use of some portion of basement has been changed to residential (barrack) , Accordingly approval from NDMC is required.

In view of above case is rejected with a request to rectify the above shortcomings at the earliest for further consideration in the matter.

Yours faithfully

(Anil Garg)
DIRECTOR
Delhi Fire Service

Copy to:

1. The Chairman, NDMC, Palika Kendra, New Delhi.