

C-15 ΔFA+F



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

75
आज़ादी का
अमृत महोत्सव

No. F6/DFS/MS/School/2025/NDZ/135

Dated: 05/03/2025

To,

The Principal,
Majeedia Model School
C- 41/5, Jama Masjid Marg,
North Ghonda, Delhi - 110094.

Subject: - Inspection Report in r/o Majeedia Model School located at C- 41/5, Jama Masjid Marg, North Ghonda, Delhi - 110094.

Sir,

Please refer to your outdoor diary no. 12645 dated 19/02/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 27/02/2025 and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/School/2015/700 dated 10/04/2015 (copy enclosed).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Encl: as above

(ATUL GARG)
DIRECTOR
o/c DELHI FIRE SERVICE

Copy to: -

1. The Dy. Director of Education, B - Block, Yamuna Vihar, Delhi - 110053.

C-11

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE NEW DELHI-110001

No. F6/DFS/MS/school/2015/700

Dated 10/04/15

To,
The Principal,
Majeedia Model School,
C-41/5, Jama Maszid Marg,
North Ghonda, Delhi-110053

Subject: - Regarding Fire Safety Certificate.

Sir,
This is in reference to your letter no.-M.M.S./ dated-07/03/2015 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above-mentioned school from fire safety point of view in presence of Mr. Riaz Ahmed (Manager). During the course of inspection, the following points / shortcomings were noticed in the school building comprising of ground plus two upper floors.

1. Width of staircase 1.50 meter not provided.
2. Hose reels not provided at each floor as required.
3. A fire pump having 450 LPM output at 40 meters head not provided.
4. Over Head water storage tank 10,000 ltrs. capacity not provided at terrace for fire fighting.
5. Exit signages not provided.

In view of above, the school building can not be considered for grant of fire safety certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully



(Rajesh Panwar)
Dy. Chief Fire Officer
Ph.011-23412025

O/C



Copy to:-
The Dy. Director of Education,
B-Block, Yamuna Vihar,
Delhi- 110053.