

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE**  
**NEW DELHI-110 001.**

No. F.6/DFS/MS/School/2025/SZ/123

Dated: 07/02/2025

**FIRE SAFETY CERTIFICATE**

Certified that the **M.C. Primary (Co-ed) School** located at Goyla More, Deendarpur, Najafgarh, New Delhi-110043, comprised of ground plus two upper floors was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/School/SZ/2022/178 dated 17.02.2022 (for two blocks). The School building was re-inspected by the officer concerned of this department on dated 24.01.2025 in the presence of Mrs. Shushma Sharma (HOS) and found that the building department (MCD) likely demolished one block (G+1 floor) and building have deemed complied the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (**ground plus two upper floors**) is fit for occupancy class "**Educational**" w.e.f. 07/02/2025 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on 07/02/2025 at New Delhi by.

  
 (Anil Garg)  
 Director  
 Delhi Fire Service

Copy to: -

1. The HOS, M.C. Primary (Co-ed) School located at Goyla More, Deendarpur, Najafgarh, New Delhi-110043.
2. Director of Education, MCD, Dr. S.P. Mukherjee Civic Centre, New Delhi- 110002.

**Conditions for the validity of fire safety certificate: -**

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
4. The trained staff should be available round the clock.
5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in).
8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

N/24

### INSPECTION REPORT

1. Name & address of the building : MCPS Co-ed School, Deendarpur-I/II, Najafgarh, New Delhi-110043.
2. Type of Occupancy : Educational
3. Building Comprised of : Two blocks, one block comprised of G+1 upper floor & 2<sup>nd</sup> block comprised of G+2 upper floors (G+1 floor block likely demolished by MCD)
4. Type of Case : Renewal
5. Details of Previous NOC : F.6/DFS/MS/School/SZ/2022/178 dated 17.02.2022 (for both blocks)
6. Fire Safety directives letter No : N/A
7. Date of inspection : 24.01.2025
8. Name of Inspecting Officer : A.D.O. R.K. Yadav
9. Name and designation of officers  
From the building side : Smt. Sushma Sharma (HOS)
10. Year of Construction : 2013-14
11. Applicant's letter No. : Online email ID [mcpsdeenpur1@gmail.com](mailto:mcpsdeenpur1@gmail.com) dated 04.12.2024

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC requirements	Provided at site	Remarks MR/NMR
1.	<b>Access to building</b>			
	<ul style="list-style-type: none"> <li>Road width</li> <li>Gate width</li> <li>Width of internal road</li> </ul>	Accessible 06 mtrs 4.5 mtrs. N/A	09 mtrs Directly accessible from road N/A	M/R MR N/A
2.	<b>Number, Width, Type &amp; Arrangement of Exits</b>			
	a. Number of staircases			
	<ul style="list-style-type: none"> <li>Upper Floors</li> <li>Basements</li> </ul>	02 No.'s N/A	Provided N/A	M/R N/A
	b. Width of staircases			
	<ul style="list-style-type: none"> <li>Upper Floor</li> <li>Basements</li> </ul>	1.50 m N/A	1.55 & 1.55 m N/A	MR N/A
	c. Protection of exits			
	<ul style="list-style-type: none"> <li>Fire check door</li> <li>Pressurization</li> </ul>	N/A N/A	N/A N/A	N/A N/A
	d. No. of continuous staircases to terrace			
	e. Width of Corridor	Required	Two	M/R
	f. Door Size	1.50 m 1.0 m	2.20 cms 1.10 m (double doors)	M/R M/R
3.	<b>Compartmentation</b>			
	<ul style="list-style-type: none"> <li>Fire check door</li> <li>Sealing of electrical shafts</li> <li>Fire Rating of shaft door</li> <li>Water Curtain</li> <li>Fire Dampers</li> </ul>	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A
4.	<b>Smoke Management System</b>			
	<ul style="list-style-type: none"> <li>Basements</li> <li>Upper floors</li> </ul>	N/A Required	N/A Natural ventilation provided	N/A M/R
5.	<b>Fire Extinguishers</b>			
	<ul style="list-style-type: none"> <li>Total numbers</li> <li>Types</li> <li>IS marking</li> </ul>	07 no's ABC/CO <sub>2</sub> type ISI marked	Provided Provided Provided	MR MR MR
6.	<b>First-Aid Hose Reels</b>			
				MR



N/26


MR  
MR  
MR

17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area.			
	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19.	Fire Control Room			
	• Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel	N/A	N/A	N/A
	• PA System Panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found not functional at the time of inspection. The shortcomings issued by this department vide letter No. F.6/DFS/MS/School/2024/SZ/774 dated 19.11.2024 have been rectified.

Note: - Earlier, FSC issued by this department vided letter No. F.6/DFS/MS/School/SZ/2022/178 dated 17.02.2022 for school building having two blocks, one block comprised of G+1 floor and 2<sup>nd</sup> block comprised of G+2 upper floors. But now the building department (MCD) likely to demolish G+1 floor block and school running only G+2 upper floors.


In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F.6/DFS/MS/School/SZ/2022/178 dated 17.02.2022 (for both blocks), renewal under rule, 37 of the Delhi Fire Service Rules, 2010 is recommended.


  
Signature of Inspecting Officer  
Name: - R.K. Yadav  
Designation: - ADO (JKP)

DO (South West)



20.1.25

CFO /   
31/01/2025

Director   
31/1/25  
ADDO