

c/194





**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001**

No F 6 / DFS / MS / 2025 /EH/SZ/ 71

Dated: 24/02/2025

**FIRE SAFETY CERTIFICATE**

Certified that the **M/s Narangs International Hotels Pvt. Ltd. Unit: The Ambassador Sky Chef** located at IGI Airport Complex, Near Centaur Hotel, New Delhi-110037, comprised of **Basement & Ground floor** was issued FSC by this department vide letter No F6/DFS/MS/EH/2022/SZ/04 dated 11.01.2022. The premise was re-inspected by the officer concerned of this department on 17.02.2025 in the presence of **Sh. D.S. Dogra (CSO)** and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have therefore deemed complied with fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premise is fit for occupancy "**Assembly (Eating House, Catering)**" with effect from 24/02/2025. And valid up to 31/03/2028 in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40, subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 24/02/2025 at New Delhi, by

  
( Atal Garg )  
Director

Delhi Fire Service

Copy to: -

1. Sh. Murali Krishnan, M/s Narangs International Hotels Pvt. Ltd. Unit: The Ambassador Sky Chef located at IGI Airport Complex, Near Centaur Hotel, New Delhi-110037.
  2. The Dy. Health Officer, South MCD, Public Health Department, Najafgarh Zone, Near Dhansa Stand, New Delhi- 110043.
- Ref: (MCD Portal, ID No. 2025020301402).

**Conditions for the validity of Fire Safety Certificate:**

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. The owner/occupier shall apply for renewal of this Fire Safety Certificate through MHA portal (<https://www.delehlhlic.gov.in>) along with a copy of this Certificate, six months prior to its expiry".
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
8. Basement shall be used as per building bye laws.

## INSPECTION REPORT

1. Name & address of the building : Narangs International Hotels Pvt. Ltd. Unit : The Ambassador Sky Chef at IGI Airport Complex, Near Centaur Hotel, New Delhi-110037.  
 2. Type of Occupancy : Assembly (Eating House, Catering).  
 3. Building Comprised of : Basement & Ground floor.  
 4. Type of Case : Renewal  
 5. Details of Previous NOC : F6/DFS/MS/EH/2012/SZ/04 Dated 11/01/2022  
 6. Fire Safety directives letter No : Nil  
 7. Date of inspection : 17/02/2025  
 8. Name of Inspecting Officer : R.K.Sinha, ADO (BW)  
 9. Name and designation of officers : Sh. D.S. Dogra (CSO)  
 From the building side : 1983 as per MCD Portal  
 10. Year of Construction : MCD Portal ID No. 2025020301402 dated 04/02/2025  
 11. Applicant's letter No.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	As per Requirement letter dated 11/01/2022	Provided at site	Remarks MR/NMR
1.	<b>Access to building</b>			
	Road width	9 m	Provided	MR
	Gate width	5 m	Provided	MR
	Width of internal road	NA	NA	NA
2.	<b>Number, Width, Type &amp; Arrangement of Exits</b>			
	Number of staircases			
	Upper Floors	NA	NA	NA
	Basements	03	Provided	MR
	Width of staircases			
	Upper Floor	NA	NA	NA
	Basements	1.2 m	1.8 m, 2.6 m & 1.2 m	MR
	Protection of exits			
	Fire check door	Required	Provided	MR
	Pressurization	NA	NA	NA
	No. of continuous staircases to terrace	Required	One	MR
	Width of Corridor	NA	NA	NA
	Door Size	NA	NA	NA
3.	<b>Compartmentation</b>			
	Fire check door	Required	Provided	MR
	Sealing of electrical shafts	Required	Provided	MR
	Fire Rating of shaft door	NA	NA	NA
	Water Curtain	NA	NA	NA
	Fire Dampers	NA	NA	NA
4.	<b>Smoke Management System</b>			
	Basements	Required	Provided	MR
	Upper floors	Required	Provided	MR
5.	<b>Fire Extinguishers</b>			
	Total numbers	Required	30 Nos.	MR
	Types	ABC/Co2 Type	Provided	MR
	IS marking	Required	Provided	MR
6.	<b>First-Aid Hose Reels</b>			
	Total numbers on each floor	B-03, G.F.- 05	Provided	MR
	Length of hose reel hose	30 m	Provided	MR
	Nozzle diameter	5 mm	Provided	MR
7.	<b>Automatic fire detection and alarming system</b>			
	Type of detectors	Required	Smoke & Heat	MR
	Location of Main Panel	Required	G.F.	MR
	Location of Repeater Panel	Required	Provided	MR
	Alternate source of power	Required	Provided	MR
	Hooters' Location	Required	Provided	MR
8.	<b>MOEFA</b>			
		Required	All Area	MR
		Required	Provided	MR

p-31

9.	<b>Public Address System</b>	Required	Provided	
10.	<b>Automatic Sprinkler System</b>			MR
	Basement	Required	Provided	NA
	Upper Floor	NA	NA	NA
	Sprinkler above false ceiling	NA	NA	
11.	<b>Internal Hydrants</b>			MR
	Size of riser/down-comer	100 mm	Provided	MR
	Number of hydrants per floor	B- 03, G.F.- 05	Provided	MR
	Hose Box	B- 03, G.F.- 05	Provided	MR
12.	<b>Yard Hydrants</b>			MR
	Total number of hydrants	06	Provided	MR
	Hose Box	06	Provided	
13.	<b>Pumping Arrangements</b>			
	Ground Level			MR
	Discharge of main Pump	1800 lpm	Provided	MR
	Head of Main pump	56 m	Provided	
	Number of main pumps	02 Nos.	Provided	MR
	Jockey Pump out put	180 lpm	Provided	MR
	Jockey pump head	56 m	Provided	MR
	Standby Pump out put	NA	NA	NA
	Standby Pump Head	NA	NA	NA
	Auto Starting/Manual Stopping	Required	Provided	MR
	Pump House Access	Required	Provided	MR
	Terrace level			
	Discharge of pump	NA	NA	NA
	Head of the pump	NA	NA	NA
	Power Supply	NA	NA	NA
	Auto Starting of pump	NA	NA	NA
14.	<b>Captive Water Storage for fire fighting</b>			
	Underground tank capacity	1,50,000 ltrs	Provided	MR
	Draw-off connection	Required	Provided	MR
	Fire service inlet	Required	Provided	MR
	Access to tank	Required	Provided	MR
	Overhead Tank capacity	NA	NA	NA
15.	<b>Exit Signage.</b>	Required	Provided	MR
16.	<b>Provision of Lifts.</b>			
	Pressurization of Lift Shaft	NA	NA	NA
	Pressurization of Lift lobby	NA	NA	NA
	Communication In lift Car	NA	NA	NA
	Fireman's Grounding Switch	NA	NA	NA
	Lift Signage	NA	NA	NA
17.	<b>Standby power supply</b>	Required	Provided	MR
18.	<b>Refuge Area.</b>			
	Total Area	NA	NA	NA
	Location	NA	NA	NA
19.	<b>Fire Control Room</b>			
	Detector System Panel	NA	NA	NA
	Flow Switch Panel	NA	NA	NA
	PA System Panel	NA	NA	NA
	Battery backup	NA	NA	NA
	Building Floor Plans	NA	NA	NA

MR  
Special Fire Protection System for  
Protection of special Risks, if any:

Co2 Flooding system provided in HT & LT panels.

MR

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The management had rectified the shortcomings issued vide letter number F6/DFS/MS/EH/2024/WZ/247 dated 18/06/2024.

Keeping in view of deemed compliance of the minimum standards of fire prevention and fire safety measures as required under rules it is recommended to renew the Fire Safety Certificate issued vide letter number F6/DFS/MS/EH/WZ/2021/285 dated 11/10/2021 under Rule 37 of the Delhi Fire Service Rules, 2010.

ADO (B.W.)  
19/2/25

Signature of Inspecting Officer  
Name : Rajeev Kumar Sinha  
Designation : ADO/B.W.

Do (Soytha) - Pl. check compliance of shortcoming dated 31/1/25.

- This is industrial building or assembly building please clarify.

*[Signature]*  
20/2/25

ADO (Barbana)

S.No-1 - Smoke detector has been Installed in the basement by the occupier of the building. In compliance of shortcoming dated 31/1/25

S.No-2 - As per the past practice this department has always issued fsc for the occupancy in eating Home assembly only. Moreover the airport Area does not fall under the Industrial Area.

Submitted please

*[Signature]*  
ADO (B.W.)  
20/2/25

Do (Soytha)

*[Signature]*  
20/2/25

ADO (B.W.)  
21/2/25  
Director

*[Signature]*

Gal