



Dated: 17/04/2025

No. F6/DFS/MS/School/NDZ/2025/ 246

To,

The Principal,
Adarash Bal Bharti Vidyalaya
A – 19, Shiv Mandir Marg, Mandawali,
Delhi – 110094.

Subject: - Regarding grant of Fire Safety Certificate in r/o Adarash Bal Bharti Vidyalaya located at A – 19, Shiv Mandir Marg, Mandawali, Delhi – 110094.

Sir,

This has a reference to your Outdoor Diary No. 14877 dated 24/03/2025, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 05/03/2025 in the presence of Mrs. Sushma (Principal) and observed that building comprised of ground plus two upper floors.

Following shortcomings were observed during time of inspection:

1. All fire extinguishers not provided.
2. First-Aid-Hose Reel Found Removed.
3. Terrace level fire pump capacity of 220 LPM Found Removed.
4. Overhead tank of capacity 2500 liters Found Removed.
5. Exit & floors Signage's not provided at strategic location in the building.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE

Copy to:-

1. The Director of Education, East Delhi Municipal Corporation, 419, Udyog Sadan, Patparganj Industrial Area, Delhi - 110092.