



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

C/149




No. F6/DFS/MS/2026/WZ/EH/274

Dated: 30/03/2026

FIRE SAFETY CERTIFICATE

Certified that the M/s Chilis Grill Bar unit of Trimex Foods Pvt. Ltd, located at S8 & 9, 2nd floor Pacific Mall Tagore Garden, Delhi-110018, in a building comprised of Two basement, ground + 04 upper floors and Restaurant is running at S8 & 9, 2nd floor only has already been issued FSC by this department vide letter No. F.6/DFS/MS/EH/WZ/2023/369 dated 22.12.2023. The premises was re-inspected by the officer concerned of this department on 19.03.2026 in the presence of Mr. Manoj (GM) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class 'Assembly' Group D (Restaurant) for S8 & 9, 2nd floor only with effect from 30/03/2026 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 30/03/2026 at New Delhi by


30/03/26
(S. K. Dua)

Dy. Chief Fire Officer (WZ)
Delhi Fire Service

Copy to:-

1. The Commissioner, MCD, Civic centre, New Delhi: to kindly ensure the occupancy as detailed above and deviation in construction if any: Online MCD Portal ID-2026030902573 dated 09.03.2026.
2. The Authorized Signatory, M/s Chilis Grill Bar unit of Trimex Foods Pvt. Ltd, located at S8 & 9, 2nd floor Pacific Mall Tagore Garden, Delhi-110018.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doi_t_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/ http://www.delhi.gov.in/wps/wcm/connect/doi_t_fire/FIRE/Home/Forms

INSPECTION REPORT

1. Name & address of the building	M/s Chilis Grill Bar unit of Trimex Foods Pvt. Ltd, located at S8 & 9, 2 nd floor Pacific Mall Tagore Garden, Delhi-110018.
2. Type of Occupancy	Assembly
3. Comprised of building	Two basement, ground + 04 upper floors
4. Type of Case	Renewal (Restaurant is running at S8 & 9, 2 nd floor only in a Mall)
5. Details of Previous NOC	F.6/DFS/MS/EH/WZ/2023/369 dated 22.12.2023
6. Fire Safety directives letter No	-NA-
7. Date of inspection	19.03.2026
8. Name of Inspecting Officer	Ajay Kumar Sharma ADO (Wazirpur/MN)
9. Name and designation of officers From the building side	Mr. Manoj (GM)
10. Year of Construction	2010 on MCD Portal
11. Applicant's letter No.	Online application No.2026030902573 dated 09.03.2026.

Pacific Mall Tagore Garden was issued FSC vide letter No. F.6/DFS/Ms/WZ/Mall/2023/349 dated 21.07.2023

S. No	Minimum Standards on fire prevention and fire safety U/R 33	Required as per Rule 35(6) of DFS Rules 2010	Provided at site	Remarks MR/NMR
Common with the Mall				
1.	Access to building			
	• Road width	12m	Provided	MR
	• Gate width	4.5m	Provided	MR
	• Width of internal road	6m	Provided	MR
Common with the Mall				
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	02nos.	Provided by mall	MR
	• Basements	-NA-	-NA-	-NA-
	b. Width of staircases			
	• Upper Floor	1.5m each	Provided by mall	MR
	• Basements	-NA-	-NA-	-NA-
	c. Protection of exits			
	• Fire check door	-NA-	-NA-	-NA-
	• Pressurization	-NA-	-NA-	-NA-
	d. No. of continuous staircases to terrace	Required	Provided by mall	MR
	e. Width of Corridor	Required	Provided by mall	MR
	f. Door Size	Old case	1.45m & 0.86m	MR(Old case)
3.	Compartmentation			
	a) Fire check door	-NA-	Provided by mall	-NA-
	b) Sealing of electrical shafts	-NA-	Provided by mall	-NA-
	c) Fire Rating of shaft door	-NA-	Provided by mall	-NA-
	d) Water Curtain	-NA-	Provided by mall	-NA-
	e) Fire Dampers	-NA-	Provided by mall	-NA-
Common with the Mall				
4.	Smoke Management System			
	a) Basements	-NA-	-NA-	-NA-
	b) Upper floors	Required	Provided	MR
5.	Fire Extinguishers			
	a) Total numbers	05nos.	Provided	MR
	b) Types	ABC/CO2	ABC/CO2	MR
	c) IS marking	ISI marked	Yes	MR
Common with the Mall				
6.	First-Aid Hose Reels			

Ske

	a) Total numbers on each floor	Near to restaurant	Provided by mall	MR
	b) Length of hose reel hose	30mm	Provided by mall	MR
	c) Nozzle diameter	5m	Provided by mall	MR
7.	Automatic fire detection and alarming system Common with the Mall			
	a) Type of detectors	Smoke/Heat	Provided & connected with the mall	MR
	b) Location of Main Panel	Restaurant within Mall	Provided by mall	MR
	c) Location of Repeater Panel	-NA-	-NA-	-NA-
	d) Alternate source of power	Restaurant within Mall	Provided by mall	MR
	e) Hooters' Location	Restaurant within Mall	Provided by mall	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	-NA-	Provided by mall	-NA-
10.	Automatic Sprinkler System Common with the Mall			
	a) Basement	-NA-	As Above	-NA-
	b) Ground & Upper Floors	-NA-	Provided by mall	-NA-
	c) Sprinkler above false ceiling	-NA-	As Above	-NA-
11.	Internal Hydrants Common with the Mall			
	a) Size of riser/down-comer	Restaurant within Mall	Provided by mall	MR
	b) Number of hydrants per floor	Restaurant within Mall	Provided by mall	MR
	c) Hose Box	Restaurant within Mall	Provided by mall	MR
12.	Yard Hydrants			
	a) Total number of hydrants	-NA-	Provided by mall	-NA-
	b) Hose Box	-NA-	Provided by mall	-NA-
13.	Pumping Arrangements Common with the Mall			
	• Ground Level			
	➤ Discharge of main Pump	Restaurant with in mall	2850lpm	MR
	➤ Head of Main pump	Restaurant with in mall	60m	MR
	➤ Number of main pumps	Restaurant with in mall	02nos.	MR
	➤ Jockey Pump out put	Restaurant with in mall	180lpm	MR
	➤ Jockey pump head	Restaurant with in mall	60m	MR
	➤ Standby Pump out put	Restaurant with in mall	2850lpm	MR
	➤ Standby Pump Head	Restaurant with in mall	60m	MR
	➤ Auto Starting/Manual Stopping	Provided by mall	Provided	MR
	➤ Pump House Access	Provided by mall	Provided	MR
	Terrace level Common with the Mall			
	➤ Discharge of pump	900lpm	Provided by mall	MR
	➤ Head of the pump	40m	Provided by mall	MR
	➤ Power Supply	Required	Provided by mall	MR
	➤ Auto Starting of pump	Required	Provided by mall	MR
14.	Captive Water Storage for fire fighting Common with the Mall			
	• Underground tank capacity			
		Restaurant within Mall	2,00,000ltr Provided by mall	MR
	➤ Draw-off connection	Restaurant within Mall	Provided by mall	MR
	➤ Fire service inlet	Restaurant within Mall	Provided by mall	MR
	➤ Access to tank	Restaurant within Mall	Provided by mall	MR
	• Overhead Tank capacity			
		10,000ltr	Provided by mall	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts. Common with the Mall			
	a) Pressurization of Lift Shaft	-NA-	-NA-	-NA-
	b) Pressurization of Lift lobby	-NA-	-NA-	-NA-
	c) Communication In lift Car	-NA-	-NA-	-NA-

N/27

	d) Fireman's Grounding Switch	-NA-	-NA-	-NA-
	e) Lift Signage	-NA-	-NA-	-NA-
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area.	Common with the Mall		
	a) Total Area	-NA-	-NA-	-NA-
	b) Location	-NA-	-NA-	-NA-
19.	Fire Control Room			
	a) Detector System Panel	-NA-	-NA-	-NA-
	b) Flow Switch Panel	-NA-	-NA-	-NA-
	c) PA System Panel	-NA-	-NA-	-NA-
	d) Battery backup	-NA-	-NA-	-NA-
	e) Building Floor Plans	-NA-	-NA-	-NA-
20.	Special Fire Protection System for Protection of special Risks, if any:	-NA-	-NA-	-NA-

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F.6/DFS/MS/EH/WZ/2023/369 dated 22.12.2023 is recommended for renewal of FSC under rule 37 of the Delhi Fire Service rules 2010.

[Signature]
19/1/26

Signature of the Inspecting Officer
Name Ajay Kumar Sharma
Designation ADO(Wazirpur/MN)

~~DO (West)~~ *[Signature]*
19/1/26

~~By CFO (WZ)~~

[Signature]
23/03/26

~~Pr. Director~~

By CFO to *[Signature]*

~~By CFO (WZ)~~

[Signature]
23/03/26

F.T. please.

[Signature]
23/03/26

~~ADO (WZ)~~

At letter to put up for kind perusal and signature please.

~~DCFO (WZ)~~

[Signature]
20/03/26
F.P. wing

[Signature]
28/3/26

Uploaded
01/4/26 *[Signature]*