

C-35

5/8/25, 4:09 PM

Eating and Lodging License Login

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS : DELHI FIRE SERVICE, NEW DELHI - 110001**

No: F6/DFS/MS/EH/WZ/2025/215

Dated: 30/05/2025

**FIRE SAFETY CERTIFICATE**

Certified that M/s Haldiram Products Pvt. Ltd. located at Shop No. SH/GF/24, Ground Floor, NSP Pink Line MRTS Station, Delhi - 110034, restaurant is running at ground floor only owned /occupied by Haldiram Products Pvt. Ltd. was earlier granted FSC by this department vide letter No. F6/DFS/MS/EH/WZ/2022/268 dated 21.09.2022. Now, the restaurant premises was re-inspected by the officer concerned of this department on 15.05.2025 in presence of Mr. Pawan (Manager) and found that the restaurant premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy class (Group-D) "Assembly Building", restaurant at ground floor only, with effect from 30/05/2025 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on .....30/05/2025.....at New Delhi by

  
(Atul Garg)

Director  
Delhi Fire Service  
Tel: 011-23414000

**Copy to:-**

1. The Commissioner, Municipal Corporation of Delhi, Dr. SPM Civic Centre, New Delhi - 02. w.r.t. ID No. 2025050708073 dated 07.05.2025.
2. The Dy. Health Officer, MCD, Keshav Puram Zone, New Delhi.
3. The Licensee, M/s Haldiram Products Pvt. Ltd. at Shop No. SH/GF/24, Ground Floor, NSP Pink Line MRTS Station, Delhi - 110034.

**Conditions for the validity of fire safety certificate**

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
4. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
5. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in).
6. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.
8. This FSC is valid for restaurant at ground floor only.

N/12

## INSPECTION REPORT

1	Name & address of the building	M/s Haldiram Products Pvt. Ltd. at Shop No. SH/GF/24, Ground Floor, NSP Pink Line MRTS Station, Delhi - 110034.		
2	Type of occupancy	Assembly		
3	Type of case	Renewal - Haldiram restaurant is running in Pacific Mall shop No. SH/GF/24, Ground floor		
4	Details of previous FSC	F6/DFS/MS/EH/WZ/2022/268 dated 21.09.2022		
5	Fire safety direction letter no.	Nil		
6	Date of inspection	15.05.2025		
7	Name of the inspecting officers	ADO (SPM)		
8	Name of the designation of officer from the building side	Mr. Pawan (Manager)		
9	Year of construction	2016 on MCD Portal		
10	Applicant's letter no.	Online application ID No. 2025050708073 dated 07.05.2025		
S.No	<b>Minimum Standards on fire Prevention and fire safety requirements U/R 33</b>	<b>UBBL/ NBC Requirements</b>	<b>Provided at Site</b>	<b>Remarks MR/ NMR</b>
1	<b>Access To Building: (Pacific Development Corporation Ltd. Mall FSC vide letter no. F.6/DFS/MS/WZ/Mercantile/2024/254 dated 24.04.2024)</b>			
	Road width	12 m	Provided	MR
	Gate width	5 m	Provided	MR
	Width of internal road	6 m	Provided	MR
2	<b>Number, Width, Type and Arrangement of Exits: common with the mall</b>			
	<b>A</b>	<b>Number of staircases</b>		
		a	Upper floor	02 nos.
		b	Basement	NA
				Provided by Mall
				MR
	<b>B</b>	<b>Width of staircases</b>		
		a	Upper floor	Required
		b	Basement	NA
				Provided by Mall
				MR
	<b>C</b>	<b>Protection of exits</b>		
		a	Fire check door	NA
		b	Pressurization	NA
				NA
				NA
	<b>D</b>	<b>No. of continuous staircases to terrace</b>		
				NA
	<b>E</b>	<b>Width of corridor</b>		
				NA
	<b>F</b>	<b>Door size</b>		
				2.0 m & 1.5 m
				Provided
				MR
3	<b>Compartmentation:</b>			
	<b>A</b>	<b>Fire check door</b>		
				NA
	<b>B</b>	<b>Sealing of electrical shafts</b>		
				NA
	<b>C</b>	<b>Fire rating of shaft door</b>		
				NA
	<b>D</b>	<b>Water curtain</b>		
				NA
	<b>E</b>	<b>Fire dampers</b>		
				NA
				NA
4	<b>Smoke Management System:</b>			
	<b>A</b>	<b>Upper floors</b>		
				12 ACPH
				Provided
				MR
	<b>B</b>	<b>Basements</b>		
				NA
				NA

5.	<b>Fire Extinguisher:</b>			
	A	Total numbers	06 nos.	Provided
	B	Types	ABC& Co2	MR
	C	ISI marking	Required	MR
6	<b>First-Aid-Hose Reels: common with mall</b>			
	A	Total numbers at each floor	01 no.	Provided by Mall
	B	Length of hose reel hose	30 mtr.	MR
	C	Nozzle diameter	05 mm	MR
7	<b>Automatic Fire Detection And Alarming System:</b>			
	A	Type of detectors	Smoke	Provided
	B	Location of main panel	Required	MR
	C	Location of repeater panel	NA	MR
	D	Alternate source of power	Required	NA
	E	Hooters Location	Required	MR
8	<b>MOEFA:</b>			
			Required	MR
9	<b>Public Address System:</b>			
			NA	MR
10	<b>Automatic Sprinkler System: common with mall</b>			
	A	Basement	NA	NA
	B	Upper floor/ Gr. floor	Required	MR
	C	Sprinkler above false ceiling	Required	MR
11	<b>Internal Hydrants: common with mall</b>			
	A	size of riser/down-comer	150 mm	Provided by Mall
	B	Number of hydrants per floor	Required	MR
	C	Hose box	Required	MR
12	<b>Yard Hydrants:</b>			
	A	Total number of hydrants	NA	NA
	B	Hose box	NA	NA
13	<b>Pumping Arrangements:</b>			
	A	Ground level	common with mall	
	a)	Discharge of main pump	NA	common with mall
	b)	Head of main pump	NA	NA
	c)	Number of main pumps	NA	common with mall
	d)	Jockey pump out put	NA	NA
	e)	Jockey pump head	NA	common with mall
	f)	Standby pump out put	NA	NA
	g)	Standby pump head	NA	common with mall
	h)	Auto starting /manual stopping	NA	NA
	i)	Pump House Access	NA	common with mall
	B	Terrace level	common with mall	
	a)	Discharge of pump	450 LPM	MR
	b)	Head of the pump	40 m	MR
	c)	Power supply	Required	MR
	d)	Auto starting of pump	Required	MR

<b>14</b>	<b>Captive Water Storage For Fire Fighting:</b>				
	<b>A</b>	Underground tank capacity	NA	2,00,000 ltrs.	NA
	<b>B</b>	Draw-off connection	NA	Provided	NA
	<b>C</b>	Fire service inlet	Required	Provided	NA
	<b>D</b>	Access to tank	NA	Provided	<b>MR</b>
	<b>E</b>	Overhead tank capacity	20,000 ltrs.	Provided by Mall	NA
<b>15</b>	<b>Exit Signage:</b>		Required	Provided	<b>MR</b>
<b>16</b>	<b>Provision of Lifts:</b>				<b>MR</b>
	<b>A</b>	Pressurization of lift shaft	NA	NA	NA
	<b>B</b>	Pressurization of lift lobby	NA	NA	NA
	<b>C</b>	Communication in lift car	NA	NA	NA
	<b>D</b>	Firemen's grounding switch	NA	NA	NA
	<b>E</b>	Lift signage	NA	NA	NA
<b>17</b>	<b>Standby Power Supply:</b>		Required	Provided by Mall	<b>MR</b>
<b>18</b>	<b>Refuge Area:</b>				
	<b>A</b>	Total area	NA	NA	NA
	<b>B</b>	Location	NA	NA	NA
<b>19</b>	<b>Fire Control Room :</b>				
	<b>A</b>	Detector system panel	NA	NA	NA
	<b>B</b>	Flow switch panel	NA-	NA	NA
	<b>C</b>	Pa system panel	NA	NA	NA
	<b>D</b>	Battery backup	NA	NA	NA
	<b>E</b>	Building floor plans	NA	NA	NA
<b>20</b>	<b>Special Fire Protection Systems For Protection of Special Risks, If Any:</b>		Required	NOVEC flooding system is provided near kitchen hood & elect. Panel	<b>MR</b>

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

Shortcomings communicated vide letter no.F.6/DFS/MS/WZ/EH/2025/161 dated 16.04.2025 has been rectified.

Keeping in view of the deemed compliance of minimum standard of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/EH/WZ/2022/268 dated 21.09.2022 is recommended to be renewed (restaurant at ground floor only), under Rule 35 of the Delhi Fire Service Rules 2010.

Accordingly, DFA is put for approval and signature please.

*Sumit Kumar*  
23/05/2025

Signature of the Inspecting Officer  
Name Sumit Kumar  
Designation ADO (SPM)

~~Dy. CFO (WZ)~~

*dy*  
23/5/2025

*efo/*  
*Sumit*  
23/5/2025

*Director*  
*Sumit*  
23/5/2025

*ADO/SPM*