



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001

210

No. F.6/DFS/MS/EH/NDZ/2026/ 114

Dated: 10/02/2026

To,

Sh. Harsh Bansal,
M/s Kyaari Lounge and Skydiner Unit of Shakumbri Aatithyam,
Property no. F 2/9, 3rd floor, Krishan Nagar, Delhi-110051.

Subject:- Application for issuance of Fire Safety Certificate in r/o M/s Kyaari Lounge and Skydiner Unit of Shakumbri Aatithyam located at Property no. F 2/9, 3rd floor, Krishan Nagar, Delhi-110051.

Sir,

This has reference to MCD online application ID No. 2026010700200 dated 07/01/2026 & 2026010700204 dated 14/01/2026 on the subject cited above. In this connection, it is to inform you that the premises was visited by the officer concerned of this department on dated 20/01/2026 in presence of Sh. Harsh Bansal. The premises is comprised of Ground plus three upper floors but Restaurant is running on third floor of the building only. The following shortcomings were observed during the time of inspection.

1. Staircase of width 1.20 meter provided against the requirement of two staircase width 1.50 meter each.
2. Door size width 1.10 meter and 1.10 meter are provided against the requirement of 1.50 meter each.
3. Fire check door shall be required in the kitchen.
4. First-Aid hose reel and down-comer are provided but not functional.
5. Smoke detector not provided at 3rd floor of the building.
6. MOEFA is provided but not functional.
7. Down-comer is not provided.
8. Main pump capacity 2280 lpm head 60 meters, standby diesel pump capacity 2280 lpm head 60 meter & Jockey pump capacity 180 lpm head 60 meters are not provided.
9. Terrace pump capacity 450 lpm head 40 meter not provided
10. Underground tank capacity 1,00,000 liters not provided.
11. Overhead tank capacity 5,000 liters not provided.
12. Exit signages not provided.
13. Firemen ground switch not provided.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire Safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,



(Dr. S. K TOMAR)

DK
DY. CHIEF FIRE OFFICER
DELHI FIRE SERVICE

Copy to:-

The Commissioner, MCD, Civic Centre, New Delhi
MCD ID No. 2026010700200 & 2026010700204