

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI- 110001

No. F.6/DFS/MS/GH/2025/SZ/ 56
To

Dated: 07/02/2025

Mr. Omparkash Vishwakarma,
2A, Bhikaji Cama Place,
New Delhi 110066

Sub: Regarding renewal of FSC in r/o Mahindra Life space Developers Ltd, at 2A, Mahindra Towers, Bhikaji Cama Place, New Delhi 110066.

Sir,

This has reference with letter No nil dated 16/01/2025 received through outdoor diary no 11507 dated 16/01/2025 on the subject cited above. In this connection, the premises have been inspected by officer concerned of this department on 03.02.2025 in the presence of Mr. Omparkash to verify the present status of fire safety measures installed in the building. The fire safety arrangements were tested / checked and found following observations:-

1. First aid hose reel provided but not functional.
2. Automatic sprinkler system provided not functional.
3. Fire Fighting pumps not on auto mode.
4. Exit signage found removed at some places.
5. The pressurization of lift lobbies not working.
6. Renovation work is being carried out at upper ground floor level.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,


(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

