

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

C-17

No. F.6/DFS/MS/NDZ/school/2025/282

Dated: 25/04/2025

To

Head of School,
Delhi Municipal Corportion,
M.C.Co-Ed Primary School,
New Ranjeet Nagar, New Delhi.

**Sub: Application for issuance of fire safety certificate in respect of Delhi Municipal Corportion,
M.C.Co-Ed Primary School, New Ranjeet Nagar, New Delhi.**

Sir,

This has reference to your letter no. nil dated 22/03/25, on the subject cited above. In this regard, it is to inform you that the matter was examined and observed that this department has already informed you vide letter no F6/DFS/MS/School/2013 /2731 dated 27.12.13 wherein 06 meter road is not available for fire tender. Accordingly, FSC cannot be issued as 06 meter road is not available for fire tender movement.

Therefore , you are requested to submit the compliance of above said letter for further consideration in the matter.

Yours faithfully,

(Atul Garg)
DIRECTOR
Delhi Fire Service

Copy to :

1. Director of Education , old secretariat , New Delhi

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001
E-mail : gargatul@hotmail.com
Ph. 011-26189168

No: F.6/DFS/MS/School/2013/ 2731

Dated: 27/12/13

To

The Principal,
M.C.D Primary School,
New Ranjeet Nagar, New Delhi-110008.

Sub: - Regarding grant of Fire Safety Certificate in r/o M.C.D Primary School, New Ranjeet Nagar, New Delhi-110008

Madam,

Please refer to your letter No. Nil dated Nil on the subject cited above. In this connection, it is to inform you that the inspection of above said school premises has been carried out by officer concerned of this department on 24.12.2013 to see the compliance of the requisite Fire Safety measures. Smt. Fozia Saeed (Principal) was also present.

During the course of inspection it was observed that the school building is comprised of ground floor plus two upper floors. The upper floors are served by two staircases having width 176 cms & 116 cms respectively. The building is not approachable to the Fire Fighting vehicles and the building does not meet the required norms in the light of Delhi Fire Service Act 2007, and Rule 2010, provisions contained in NBC of India (part-IV) due to the following shortcomings: -

1. First Aid Hose Reels are not provided in the school building.
2. Fire Pump of 450 LPM discharge with 30 m head is not provided.
3. O.H water storage tank of 10000 Ltr cap. is not provided.
4. Exit Signs are not provided in the school building.
5. The school building is not approachable for fire fighting vehicles.
6. Four Co2 type Fire Extinguishers of 4.5 kg/2.2 kg capacity each and three D.C.P type Fire Extinguishers of 05 kg capacity or WCO2 type Fire Extinguishers of 09 ltr. capacity are not provided in the school building.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Faithfully

(Atul Garg)

Dy. Chief Fire Officer
Delhi Fire Service