

C/53

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No: F.6/DFS/MS/SZ/2025/1881

Dated: - 23/10/2025

To,

The Authorized Signatory,  
For Truenorth Automobiles Private Limited,  
A-73, Naraina Industrial Area,  
Phase- 1, New Delhi - 110028.



Sub.: - Regarding renewal of Fire Safety Certificate in r/o. Plot No. A-73, Naraina Industrial Area, Phase- 1, New Delhi - 110028.

Sir,

Please refer to your letter No. Nil, dated Nil, received in this office through outdoor dairy No. 6248 dated 22.09.2025, on the subject cited above. In this connection it is to inform you that the aforsaid premises have been inspected by the officer concerned of this department on dated 13.10.2025 in the presence of Manager, to check the status of the shortcomings already pointed out by this department vide letter No. F6/DFS/MS/2025/328 dated 09.07.2025. During the course of inspection, it was observed that the shortcomings are not complied.

In view of above, renewal of 'Fire Safety Certificate' cannot be considered at this stage. You are requested to rectify shortcomings under intimation to this department for taking further necessary action in this matter.

Yours faithfully

  
(A. K. Malik)  
Dy. Chief Fire Officer  
South Zone  


Copy to:-

The Dy. Commissioner, MCD, Karol Bagh Zone, Anand Parbat, New Delhi.

c/s0

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001**

No.F.6/DFS/MS/2025/ 328

Dated: 09/07/2025

To

Authorized Signatory,  
For Truenorth Automobiles Private Limited,  
A-73 Naraina Industrial Area Phase-I,  
New Delhi.

**Sub:- Regarding issuance of fire safety certificate in r/o Plot no. 73, Block No. A, Naraina Industrial Area, Phase -I, New Delhi.**

Sir,

This has reference to your letter no. nil dated 19.06.2025 & DFS diary no. 2908 dated 19.06.2025, on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 01/07/2025 in the presence of Manager and the following shortcomings were observed:-

1. Hydrant, hose reel & pump found nonfunctional.
2. Pressurization of lift/ lift lobby & Staircases is not provided.
3. Alternate staircase serving to basement is not available to other parts as basement is divided in two parts through wooden partition.
4. Temporary shed at terrace floor is added, required to be removed or sealed.

In view of above, the FSC cannot be renewed till compliance of above shortcomings at the earliest for further consideration in the matter. Further, the occupancy of building /premises in absence requisite fire & life safety arrangements shall be at the risk and liability of the owner/occupier. The statutory/licensing authority may take suitable action as deemed fit.

Yours faithfully

(Atul Gargy)  
DIRECTOR  
Delhi Fire Service

Copy to :  
The Commissioner, MCD, Civic Centre, New Delhi.