

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI- 110001

No. F.6/DFS/MS/School/2025/SZ/286

Dated: 25./04./2025

To

The Principal,
Rajeshwari Karuna School,
D-95, Sanjay Colony, Bhati Mine,
New Delhi 110074.

Sub: Regarding issuance of FSC in r/o Rajeshwari Karuna School, D-95, Sanjay Colony, Bhati Mine, New Delhi 110074.

Sir,

This has reference to your letter no RKS/AVWMER/2025/1630 dated 16/03/2025 received through outdoor diary no 255 dated 04/03/2025 on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 21.04.2025 in the presence of Mr. Anil Wilkinson (Manager) observed that as per the record available in this department, FSC of the said school was granted vide letter no F6/DFS/MS/School/2022/SZ/737 dated 05/07/2022 for Ground floor only whereas the owner of school has now added one more floor and the building is now comprised of Ground plus one upper floors. During the course of visit following observations were noticed:-

1. The access road to the premise is less than of 6m; hence the said school is not accessible to Fire tender/fire engine.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to:-

1. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-54.