



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**



No. F6/DFS/MS/2025/GH/ 20

Dated: 07 / 01 / 2026

To  
The Commissioner,  
Municipal Corporation of Delhi.

**Sub:** -Regarding issuance of fire safety certificate in r/o M/s Shri Hari Sharnam Guest House located at Second Floor, Plot No. 1490-1491, Kashmiri Gate, Delhi-110006.

Sir,

This has reference to online MCD Portal I.D. No. 2025120315364 dated 03/12/2025 on the subject cited above. In this connection this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 29/12/2025 in the presence of Mr. Vijay Kumar (Manager) to check the existing fire safety measures. During inspection it has been observed that the building is comprised of ground & 02 upper floors only. But Guest House is running at 2<sup>nd</sup> floor with 04 guest rooms & 01 Dormitory (48 beds) only. Your request for FSC is rejected under Rule 35 (3) due to following shortcomings.

- 1 There is only one staircase provided width of 1.20m against the requirement of 02 nos. staircases width of 1.50m each from ground to terrace level.
- 2 Fire check doors not provided in the building as per clause 7.31 of UBBL 2016.
- 3 The width of corridor provided is 1.20m against the requirement of 1.50m
- 4 Smoke ventilation systems are not provided.
- 5 Carbon Monoxide detector is not provided as per clause 7.31 of UBBL 2016.
- 6 MOEFA System is not provided.
- 7 Terrace level fire water tank capacity of 5,000 Ltr is provided against the requirements of 10,000 Ltr.
- 8 Exit & floors signage's is not provided in the building.

Keeping in view of above, grant of Fire Safety Certificate cannot be considered at this stage & rejected. Applicant may be requested to rectify the above mentioned shortcomings under intimation to this department; till such time running of this guest house is at your own risk & responsibility.

Yours faithfully

Dr. S.K. Tomar  
Dy. CFO (NDZ)