



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



Application ID. 52026042902608

Dated: 01-06-2026

SHORTCOMING(S)

With reference to your application ID **52026042902608** dated **01-06-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Krishna Bharti Model School** at **12, Govind Vihar, Main Karawal Nagar Road** from fire safety point of view in presence of **Umesh Chandra Sharma** on dated **25/05/2026** During the course of inspection following observations were made:-

1. An additional staircase of width 0.75 meter shall be required.
2. First Aid Hose reels not provided.
3. A terrace pump 220 lpm head 40 meters provided but not functional.
4. An overhead tank capacity 2,500 liters not provided.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

Dr.S.K.Tomar
Chief Fire Officer

Copy to:-

1. UMESH CHANDRA SHARMA , HOUSE NO-596, KRISHNA GALI NO-7 BHAJAN , ADARSH MOHALLA MAUJPUR , Delhi, 110053
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.