



c/32



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE  
NEW DELHI- 110 001**

No.F.6/DFS/MS/School/2025/NDZ/ 827

Dated: 21/11/2025

To,

The Manager,  
Abhinav Bharti Model School  
E-Block, Subhash Vihar, North Ghonda,  
Delhi-110053.

Sub:- Regarding renewal of Fire Safety Certificate r/o Abhinav Bharti Model School located at E-Block, Subhash Vihar, North Ghonda, Delhi-110053.

Sir,

This is in reference to your email id:- abhinavbhartibhawan@gmail.com dated 12/09/2025 on the subject cited above. In this connection, it is to inform you that officer concerned of this department has visited the school on dated 10/11/2025 in presence of Manager and observed that the shortcomings as communicated earlier vide letter No. F.6/DFS/MS/School/2025/NDZ/734 dated 17/09/2025 (copy enclosed) have not been complied yet.

In view of the above, Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcomings communicated vide above mentioned letter under intimation to this office for further action.

Yours faithfully,

Encl:- As above

  
20/11/25

(Dr. S. K. TOMAR)  
DY. CHIEF FIRE OFFICER (NDZ)  
DELHI FIRE SERVICE

Copy to:-

The Dy. Director of Education, B-Block, Yamuna Vihar, Delhi- 110053





GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE  
NEW DELHI- 110 001

d/31

1619  
25

No. F.6/DFS/MS/School/2025/NDZ/ 734

Dated 17/09/2025

To,

The Manager,  
Abhinav Bharti Model School,  
E-Block, Subhash Vihar, North Ghonda,  
Delhi-110053.

Sub:- Regarding renewal of Fire Safety Certificate r/o Abhinav Bharti Model School located at E-Block, Subhash Vihar, North Ghonda, Delhi-110053.

Sir,

With reference to your letter no. abhinavbhartibhawan@gmail.com dated 02/07/2025 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection on dated 30/08/2025 of the above-mentioned School from fire safety point of view in presence of the Sh. Pramod Kumar. The building comprised of Ground plus two upper floors. Following shortcomings were observed during the time of inspection.

1. First Aid house reels provided but not functional.
2. Down comers provided but not functional.
3. Terrace pump provided but not functional.
4. Exit Signages are not provided.

In view of the above, the building cannot be considered for issuance of Fire Safety Certificate at this stage. Therefore, you are requested to rectify the above-mentioned shortcomings under intimation to this office for further course of action.

Yours faithfully,

1619  
(VIRENDRA SINGH)  
CHIEF FIRE OFFICER

Copy to:-

The Dy. Director of Education,  
B-Block, Yamuna Vihar, Delhi- 110053