



No.F6/DFS/MS/School/NDZ/2025/ 1340

Dated: 21/11/2025

FIRE SAFETY CERTIFICATE

Certified that the Vanasthali Public Sr. Sec. School located at Near Ruchica Petrol Pump, Mayur Vihar, Ph-III, Delhi-96, comprised of Ground + 03 upper floors was granted Fire Safety Certificate by this department vide letter no.- F6/DFS/MS/School/NDZ/2022/1107 dated 03.10.2022. The school building was re-inspected by officer concerned of this department on 28.10.2025 in the presence of Mrs. Veena Himani (Vice Principal) and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules 2010 and that the School building (Ground + 03 upper floors) is fit for occupancy of Group B "Educational Building" with effect from21/11/2025... for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on....21/11/2025....at New Delhi by


(Dr. S.K. Tomar)

Dy. Chief Fire Officer (NDZ)
Delhi Fire Service


20/11/25

Copy to:-

1. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi
2. The Principal, Vanasthali Public Sr. Sec. School located at Near Ruchica Petrol Pump, Mayur Vihar, Ph-III, Delhi-96.

Conditions for the validity of Fire Safety Certificate

1. All the means of escape shall be kept free of all the type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
5. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
7. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

INSPECTION REPORT

1	Name & address of the building	Vanasthali Public Sr. Sec. School located at Near Ruchica Petrol Pump, Mayur Vihar Ph-III, Delhi-96.			
2	Building is comprised of	Ground + 03 upper floors			
3	Type of occupancy	Group B- Educational building			
4	Type of case	Renewal			
5	Details of previous FSC	F6/DFS/MS/School/NDZ/2022/1107 dated 03.10.2022			
6	Fire safety direction letter no.	F6/DFS/MS/BP/2002/2379 dated 09.12.2002			
7	Date of inspection	28.10.2025			
8	Name of the inspecting officers	Rajesh Kumar Shukla, ADO (L.N)			
9	Name of the designation of officer from the building side	Mrs. Veena Himani (Vice Principal)			
10	Year of construction	2002			
11	Applicant's letter no.	Outdoor diary no. 7173 dated 16.10.2025			
S.No	Minimum standard of fire prevention and fire safety U/R 33	Requirement as per Rule 35 (6)	Provided at site	Remarks MR/NMR	
1	Access to Building:				
	A	Road width	12.0 m	30.0 m	MR
	B	Gate width	4.5 m	4.5 m	MR
	C	Width of internal road	NA	NA	NA
2	Number, Width, Type and Arrangement of Exits:				
	A	Number of staircases			
	a	Upper floor	2 nos.	02 nos.	MR
	b	Basement	NA	NA	NA
	B	Width of staircases			
	a	Upper floor	1.50 m	1.50 m each	MR
	b	Basement	NA	NA	NA
	C	Protection of exits			
	a	Fire check door	NA	NA	NA
	b	Pressurization	NA	NA	NA
	D	No. of continuous staircases to terrace	01 no.	02 nos.	MR
	E	Width of corridor	1.5 m	1.5 m	MR
	F	Door size	1.0 m	1.0 m	MR
3	Compartmentation:				
	A	Fire check door	NA	NA	NA
	B	Sealing of electrical shafts	NA	NA	NA
	C	Fire rating of shaft door	NA	NA	NA
	D	Water curtain	NA	NA	NA
	E	Fire dampers	NA	NA	NA
4	Smoke Management System:				
	A	Basement	NA	NA	NA
	B	Upper floor	NA	NA	NA
5.	Fire Extinguisher:				
	A	Total numbers	15 nos.	16 nos.	MR
	B	Types	CO ₂ & ABC	CO ₂ & ABC	MR
	C	ISI marking	ISI marked	Provided	MR
6	First-Aid-Hose Reel:				
	A	Total numbers of each floor	02 nos.	02 nos.	MR
	B	Length of hose reel hose	30 mm	30 mm	MR
	C	Nozzle diameter	05 mm	05 mm	MR

7	Automatic Fire Detection and Alarming System:				
	A	Type of detectors	NA	NA	NA
	B	Location of main panel	NA	NA	NA
	C	Location of repeater panel	NA	NA	NA
	D	Alternate source of power	NA	NA	NA
	E	Hooters	NA	NA	NA
8	MOEFA:		NA	NA	NA
9	Public Address System:		Required	Provided	MR
10	Automatic Sprinkler System:				
	A	Basement	NA	NA	NA
	B	Upper floor	NA	NA	NA
	C	Sprinkler above false ceiling	NA	NA	NA
11	Internal Hydrants:				
	A	Size of riser/down-comer	100 mm	100 mm	MR
	B	Number of hydrants per floor	02 nos.	02 nos.	MR
	C	Hose box	02 nos.	02 nos.	MR
12	Yard Hydrants:				
	A	Total number of hydrants	NA	NA	NA
	B	Hose box	NA	NA	NA
13	Pumping Arrangements:				
A	Ground level				
	a)	Discharge of main pump	NA	NA	NA
	b)	Head of main pump	NA	NA	NA
	c)	Number of main pumps	NA	NA	NA
	d)	Jockey pump out put	NA	NA	NA
	e)	Jockey pump head	NA	NA	NA
	f)	Standby pump out put	NA	NA	NA
	g)	Standby pump head	NA	NA	NA
	h)	Auto starting /manual stopping	NA	NA	NA
	i)	Pump house access	NA	NA	NA
B	Terrace Level				
	a)	Discharge of pump	450 LPM	2 nos. of 450 LPM	MR
	b)	Head of the pump	40 m	40 m	MR
	c)	Power supply	Required	Provided	MR
	d)	Auto starting of pump	Required	Provided	MR
14	Captive Water Storage for Fire Fighting:				
	A	Underground tank capacity	50,000 ltrs	50,000 ltrs	MR
	B	Draw-off connection	Required	Provided	MR
	C	Fire service inlet	Required	Provided	MR
	D	Access to tank	Required	Provided	MR
	E	Overhead tank capacity	10,000 ltrs	20,000 ltrs	MR
15	Exit Signage:		Required	Provided	MR
16	Provision of Lifts:				
	A	Pressurization of lift shaft	NA	NA	NA
	B	Pressurization of lift lobby	NA	NA	NA
	C	Communication in lift car	NA	NA	NA
	D	Firemen's grounding switch	NA	NA	NA
	E	Lift signage	NA	NA	NA
17	Standby Power Supply:		NA	NA	NA
18	Refuge Area:				
	A	Total area	NA	NA	NA
	B	Location	NA	NA	NA
19	Fire Control Room:				
	A	Detector system panel	NA	NA	NA
	B	Flow switch panel	NA	NA	NA
	C	PA system panel	NA	NA	NA
	D	Battery backup	NA	NA	NA
	E	Building floor plans	NA	NA	NA

20	Special Fire Protection systems for protection of special Risks, if any:		NA
----	--	--	----

LEGENDS:-Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/School/NDZ/2022/1107 dated 03.10.2022 is recommended to be renewed.

[Signature]
29/11/25

Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (L.N)

DO (East) *[Signature]*
3/11/25

Dy. CEO (NDZ)

[Signature]
19/11/25

Principal Director

Dy. CEO to Comm.

Dy. CEO (NDZ)

[Signature]
19/11/25

ADO/LN

[Signature]
20/11/25

It is put up pls

[Signature]
20/11/25

Dy. CEO (NDZ)

[Signature]
20/11/25

SMS