

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI- 110001

No.F6/DFS/MS/School/NDZ/2025/1267

Dated: 29/10/2025

FIRE SAFETY CERTIFICATE

Certified that The Bengali Senior Sec. School located at 22-A, Shyam Nath Marg, New Delhi- 110054, comprised of Two Blocks 1. (Ground + first floor) & 2. (ground floor only) owned/ occupied by The Bengali Senior Sec. School was granted FSC by this department vide letter no.F6/DFS/MS/School/NDZ/2022/870 dated 10.08.2022. The premises was re-inspected by the officer concerned of this department on 04.09.2025 in the presence of Mrs. Rachna (Principal) and found that the premises/building have deemed complied with the fire prevention and fire safety requirements in accordance with the circular issued by the Director of Education dated 01.03.2011 that the building is fit for occupancy class (Group-B) "Educational Building" with effect from ..29/10/2025...for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to conditions under rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on29/10/2025.....at New Delhi by

(Signature)
29/10/25

(Dr. S. K. Tomar)
Dy. Chief Fire Officer
Delhi Fire Service

o/c 8/25/10

Copy to:-

1. The Director of Education,
Govt. of NCT of Delhi, Old Secretariat, Delhi.
2. The Principal, The Bengali Senior Sec. School at 22-A, Shyam Nath Marg, New Delhi- 110054.

Conditions for the validity of Fire Safety Certificate

1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
2. All the means of escape shall be kept free of all the type of obstruction all the time.
3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1	Name and address of the building:	The Bengali Senior Secondary School, 22-A, Sham Nath Marg, Delhi – 110054.
2	Type of occupancy with details of floors:	“Educational Building” (Group -B) (Two Blocks -1. (ground + 01 upper floor) & 2. (ground floor only)
3	Type of case:	Renewal case
4	Details of previous FSC:	F6/DFS/MS/School/NDZ//2022/870 dated 10.08.2022
5	Fire safety directives no.:	NA
6	Date of inspection:	04.09.2025
7	Name of the inspecting officer:	ADO (SPM)
8	Name and designation of the officer from the building side:	Mrs. Rachna (Principal)
9	Year of construction:	1968
10	Reference letter no.:	Outdoor diary No. 5306 dated 26.08.2025

S. No	Minimum Standards on fire Prevention and fire safety requirements U/R 33	As per Education Circular	Provide at site	Remarks MR/NM/R
1	Access to Building			
	A Road width	Required	07 m	MR
	B Gate width	4.5 m	06 m	MR
	C Width of internal roads	NA	NA	NA
2	Number, Width, Type & Arrangement of Exits			
	A No. of Staircase:			
	a) Upper floor	03 nos.	03 nos.	MR
	b) Basements	NA	NA	NA
	B Width of the Staircase:			
	a) Upper floor	1.40 m	1.52 m, 1.66 m & 1.35 m	MR
	b) Basements	NA	NA	NA
	C Protection of Exits			
	a) Fire check door	NA	NA	NA
	b) Pressurization	NA	NA	NA
	D No. of continuous staircase to terrace:	NA	NA	NA
	F Width of the corridor	NA	NA	NA
	E Door size	NA	NA	NA
3	Compartmentation:			
	A Fire check doors	NA	NA	NA
	B Sealing of electrical shafts	NA	NA	NA
	C Fire rating of shaft doors	NA	NA	NA
	D Water curtain	NA	NA	NA
	E Fire dampers	NA	NA	NA
4	Smoke management System:			
	A Basements	NA	NA	NA
	B Upper floors	12 ACPH	Natural/ Ventilated	NA
5	Fire extinguishers			
	A Total numbers	15 nos.	15 nos.	MR
	B Types	Co2 & ABC	Co2 & ABC	MR
	C ISI marking	Required	Provided	MR

6	First Aid Hose reel				
	A	Total no. at each floor	1 no.	1 no.	MR
	B	Length of Hose Reel	30 m	30 m	MR
	C	Nozzle diameter	05 mm	05 mm	MR
7	Automatic Fire Detection and Alarm System (ADAS)				
	A	Type of Detectors	NA	NA	NA
	B	Location of main Panel	NA	NA	NA
	C	Location of Repeater Panel	NA	NA	NA
	D	Alternate power Source	NA	NA	NA
	E	Hooter's location	NA	NA	NA
8	MOEFA				
9	Public Address System				
10	Automatic Sprinkler System				
	A	Basement	NA	NA	NA
	B	Upper Floor	NA	NA	NA
	C	Sprinklers above false ceiling	NA	NA	NA
11	Internal hydrants				
	A	Size of the riser/down comer	100 mm	100 mm	MR
	B	No. Of hydrants per floor	01 no.	01 no.	MR
	C	Hose box	01 no.	01 no.	MR
12	Yard Hydrants				
	A	Total no. of hydrants	NA	NA	NA
	B	Hose box	NA	NA	NA
13	Pumping arrangements				
	A	Ground Level			
		a) Discharge of main pump	NA	NA	NA
		b) Head of main pump	NA	NA	NA
		c) Number of main pump	NA	NA	NA
		d) Discharge of jockey pump	NA	NA	NA
		e) Head of jockey pump	NA	NA	NA
		f) Discharge of Standby pump	NA	NA	NA
		g) Head of Standby pump	NA	NA	NA
		h) Auto starting/ manual stopping	NA	NA	NA
	B	Terrace Level			
		a) Discharge of terrace pump	450 LPM	450 LPM	MR
		b) Head of terrace pump	40 m	40 m	MR
		c) Alternate power supply	Required	Provided	MR
		d) Auto starting of pump	Required	Provided	MR
14	Captive Water Storage for Fire Fighting				
	A	Underground tank capacity	NA	NA	NA
	B	Draw off connection	NA	NA	NA
	C	Fire Service Inlet	NA	NA	NA
	E	Access to tank	NA	NA	NA
	D	Overhead tank capacity	10,000 ltrs.	10,000 ltrs.	MR
15	Exit Signage				
			Required	Provided	MR
16	Provision of lift				
	A	Pressurization of lift shaft	NA	NA	NA
	B	Pressurization of lift lobby	NA	NA	NA
	C	Communication in lift car	NA	NA	NA
	D	Fireman switch	NA	NA	NA
	E	Lift signage	NA	NA	NA
17	Standby Power Supply				
			Required	Provided	MR

18	Refuge Area		NA	NA	NA
A	location		NA	NA	NA
B	Total area		NA	NA	NA
19	Fire Control Room		NA	NA	NA
A	Fire Detection System panel		NA	NA	NA
B	Flow switch panel		NA	NA	NA
C	P A system panel		NA	NA	NA
D	Battery backup		NA	NA	NA
E	Building floor plan		NA	NA	NA
20	Special Fire Protection for special risk if any: 04 Sand Buckets Provided				MR

The fire protection systems provided in the school were tested, checked at random found functional at the time of inspection.

Shortcomings communicated vide letter No.F6/DFS/MS/School/NDZ/2025/565 dated 03/07/2025 have been rectified.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required as per Director Education, Circular FSC issued vide letter no. F6/DFS/MS/School/NDZ//2022/870 dated 10.08.2022, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Sumit Kumar
08/09/2025

Signature of the Inspecting Officer
Name Sumit Kumar
Designation ADO (SPM)

DO/CD)

W
8/9/25
Dy. CPO (NDZ)

Kirp
09/09/25

CFO

11/9/2025

Principal Dineeta

Dy. CPO to Bank.

Dy. CPO (NDZ)

17/10/25

CFIOMR
23/10/25

A DO (SPM)

f.T. letter is put up for signature, please.

Dy. CPO (NDZ)

CFIOMR
28/10/25

Sumit Kumar
25/10/2025

MS