

c96



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001



No F 6 / DFS / MS / 2025/EH/WZ/05

Dated: 03/01/2025

FIRE SAFETY CERTIFICATE

Certified that the **Boussac (A Unit of NG Warehouse Pvt. Ltd.)** located at **3rd Floor, 13-C, NWA, West Punjabi Bagh, Delhi-110026** was issued FSC by this department vide letter No F6/DFS/MS/EH/WZ/2021/205 dated 31.08.2021. The premise was re-inspected by the officer concerned of this department on 19.12.2024 in the presence of **Sh. Manoj (Manager)** and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have therefore deemed complied with fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premise is fit for occupancy "**Assembly (Restaurant)**" **Group D (for third floor only)** with effect from ...03.01.2025. For a period of three years in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40, subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on03.01.2025 at New Delhi, by

(Atul Garg)
Director
Delhi Fire Service

Copy to: -

1. Boussac (A Unit of NG Warehouse Pvt. Ltd.) located at 3rd Floor, 13-C, NWA, West Punjabi Bagh, Delhi-110026.
2. MHA Portal, ID No. 2024120917801.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. The owner/occupier shall apply for renewal of this Fire Safety Certificate through MHA portal (<https://www.delhihlic.gov.in>) along with a copy of this Certificate, six months prior to its expiry".
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
8. This FSC is valid for Third Floor only.

INSPECTION REPORT

1. Name & address of the building : M/s Boussac (A Unit of NG Warehouse Pvt. Ltd.) located at Shop/Property No. 13-C, 3rd Floor, NWA, Club Road, West Punjabi Bagh, Delhi- 110026.
2. Type of Occupancy : Assembly (Restaurant) at 3rd Floor.
3. Building Comprised of : Basement, Stilt, Upper Ground plus three upper floors.
4. Type of Case : Renewal
5. Details of Previous NOC : F6/DFS/MS/EH/WZ/2021/205 Dated 31/08/2021
6. Fire Safety directives letter No : Nil
7. Date of inspection : 19/12/2024
8. Name of Inspecting Officer : R.K.Sinha, ADO (BW)
9. Name and designation of officers
From the building side : Sh. Manoj (Manager)
10. Year of Construction : 2014 aas per N-20
11. Applicant's letter No. : MHA Application ID No. 2024120917801 dated 10/12/2024

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Required as per Rule 35(6) of DFS Rule 2010	Provided at site	Remarks MR/NMR
1.	Access to building			
	Road width	12 m	Provided	MR
	Gate width	4.5 m	On Road	MR
	Width of internal road	NA	NA	NA
2.	Number, Width, Type & Arrangement of Exits			
	Number of staircases			
	Upper Floors	02	Provided	MR
	Basements	NA	NA	NA
	Width of staircases			
	Upper Floor	1.5 m each	Provided	MR
	Basements	NA	NA	NA
	Protection of exits	NA	NA	NA
	Fire check door	NA	NA	NA
	Pressurization	NA	NA	NA
	No. of continuous staircases to terrace	NA	NA	NA
	Width of Corridor	NA	NA	NA
	Door Size	2 × 1.5 m	Provided	MR
3.	Compartmentation			
	Fire check door	Required	Provided	MR
	Sealing of electrical shafts	NA	NA	NA
	Fire Rating of shaft door	NA	NA	NA
	Water Curtain	NA	NA	NA
	Fire Dampers	NA	NA	NA
4.	Smoke Management System			
	Basements	NA	NA	NA
	Upper floors	Required	Provided	MR
5.	Fire Extinguishers			
	Total numbers	06 No.	Provided	MR
	Types	ABC/Co2 Type	Provided	MR
	IS marking	Required	Provided	MR
6.	First-Aid Hose Reels			
	Total numbers on each floor	01	Provided	MR
	Length of hose reel hose	30 m	Provided	MR
	Nozzle diameter	5 mm	Provided	MR
7.	Automatic fire detection and alarming system			
	Type of detectors	Required	Provided	MR
	Location of Main Panel	Required	Provided	MR
	Location of Repeater Panel	Required	Required	MR
	Alternate source of power	Required	Provided	MR
	Hooters' Location	Required	Provided	MR
8.	MOEFA			
		Required	Provided	MR

N-26

9.	Public Address System	NA	NA	NA
10.	Automatic Sprinkler System	NA	NA	NA
	Basement			NA
	Upper Floor	NA	NA	NA
	Sprinkler above false ceiling	NA	NA	NA
11.	Internal Hydrants			
	Size of riser/down-comer	100 mm	Provided	MR
	Number of hydrants per floor	01	Provided	MR
	Hose Box	01	Provided	MR
12.	Yard Hydrants			
	Total number of hydrants	NA	NA	NA
	Hose Box	NA	NA	NA
13.	Pumping Arrangements			
	Ground Level			
	Discharge of main Pump	2280 lpm	Provided	MR
	Head of Main pump	70 m	Provided	MR
	Number of main pumps	01	Provided	MR
	Jockey Pump out put	180 lpm	Provided	MR
	Jockey pump head	70 m	Provided	MR
	Standby Pump out put	2280 lpm	Provided	Instead of D.G. Pump electrical pump of same capacity is provided (MR)
	Standby Pump Head	70 m	Provided	MR
	Auto Starting/Manual Stopping	Required	Provided	MR
	Pump House Access	Required	Provided	MR
	Terrace level			
	Discharge of pump	450 lpm	Provided	MR
	Head of the pump	40 m	Provided	MR
	Power Supply	Required	Provided	MR
	Auto Starting of pump	Required	Provided	MR
14.	Captive Water Storage for fire fighting :			
	Underground tank capacity	100,000 ltrs	Provided	MR
	Draw-off connection	NA	NA	NA
	Fire service inlet	Required	Provided	MR
	Access to tank	NA	NA	NA
	Overhead Tank capacity	5,000 ltrs	Provided	MR
	Required	Required	Provided	MR
15.	Exit Signage.			MR
16.	Provision of Lifts.			
	Pressurization of Lift Shaft	NA	NA	NA
	Pressurization of Lift lobby	NA	NA	NA
	Communication In lift Car	Required	Provided	MR
	Fireman's Grounding Switch	Required	Provided	MR
	Lift Signage	Required	Provided	MR
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area.			
	Total Area	NA	NA	NA
	Location	NA	NA	NA
19.	Fire Control Room			
	Detector System Panel	NA	NA	NA
	Flow Switch Panel	NA	NA	NA
	PA System Panel	NA	NA	NA
	Battery backup	NA	NA	NA
	Building Floor Plans	NA	NA	NA

20.	Special Fire Protection System for Protection of special Risks, if any:	NA	NA	NA
-----	---	----	----	----

N-27

One office at terrace is sealed by brick wall by owner/ occupier.
 The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The management had rectified the shortcomings issued vide letter no. F6/DFS/MS/WZ/EH/2024/496 dated 05/11/2024.
 Keeping in view of deemed compliance of the minimum standards of fire prevention and fire safety measures as required under rules it is recommended to renew the Fire Safety Certificate issued vide letter number F6/DFS/MS/EH/WZ/2021/205 dated 31/08/2021 under rule 37 of Delhi Fire Service Rules, 2010.

[Signature]
 Signature of Inspecting Officer
 Name : Rajeev Kumar Sinha
 Designation : ADO/B.W.

Dyctf (WZ)

Where is the undertaking & photo of office at terrace floor?

Ado (Bangna)

[Signature]
 23/12/2024

Sir, undertaking and photo of office at terrace floor is placed at C-93 & C-94. Submitted for
 Signi Mean!

[Signature]
 ADO (WZ)
 27/12/24

Dyctf (WZ)

~~Spec~~
 please see the undertaking & photographs without mentioning floor.

[Signature]
 30/12/2024

DCFO/.....
 Dated: 30/12/2024

CTD
Director
[Signature]
 31/12/2024

[Signature]