




No. F6/DFS/MS/SCHOOL/SZ/2025/ 1407

Dated: 19/12/2025

FIRE SAFETY CERTIFICATE

Certified that the Daisy Dales Sr. Sec. School at E - 331A, East of Kailash, New Delhi - 110065 comprised of Basement, Ground plus three upper floors was earlier granted Fire Safety Certificate by this department vide letter No. F6/DFS/MS/School/SZ/2022/906 dated 18/08/2022. Now the school building was re-inspected by Assistant Divisional Officer (M. Road) from this department on 09/12/2025 in presence of Mr. Sada Shiv (Manager) and found that the building has deemed complied with the fire prevention and fire safety requirements in accordance with Directorate of Education Circular No F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 issued by Director of education. Govt. of NCT of Delhi and that the premises is fit for occupancy of "Educational Building" with effect from 19/12/2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance under Rules 28 of Delhi Fire Service Rule, 2010 printed below.

Issued on 19/12/2025 at New Delhi by.


(A.K. Malik)
Dy. Chief Fire Officer
Delhi Fire Service
o/c(w)

Copy to: -

1. The Director of Education, Govt of NCT of Delhi, Old Secretariat, Delhi – 110054.
2. The Principal, Daisy Dales Sr. Sec. School at E-331A, East of Kailash, New Delhi – 110065.

Conditions for the validity of Fire Safety Certificate

1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
2. All the means of escape shall be kept free of all the type of obstruction all the time.
3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

1	Name & address of the building	Daisy Dales Sr. Sec. School at E - 331A, East of Kailash, New Delhi - 110065.
2	Building is comprised of	Basement, Ground plus three upper floors
3	Type of occupancy	Educational Building (Group -B)
4	Type of case	Renewal Case
5	Details of previous FSC	F6/DFS/MS/School/SZ/2022/906 dated 18/08/2022
6	Fire safety directives letter no.	F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011
7	Date of inspection	09/12/2025
8	Name of the inspecting officers	Yashwant Singh Meena, ADO/Mathura Road
9	Name of the designation of officer from the building side	Mr. Sada Shiv (Manager)
10	Year of construction	1984
11	Applicant's letter no.	Outdoor Dairy No. 8477 dated 18/11/2025

S. No	Minimum standard of fire prevention and fire safety U/R 33	DOE Requirement	Provided at site	Remarks MR/NMR
1	Access to Building:			
A	Road width	6.0 meters.	Provided	MR
B	Gate width	N/A	N/A	N/A
C	Width of internal road	N/A	N/A	N/A
2	Number, Width, Type and Arrangement of Exits:			
A	Number of staircases			
a	Upper floor	01 No.	02 Nos.	MR
b	Basement	02 Nos	02 Nos	MR
B	Width of staircases			
a	Upper floor	1.5m/0.75m	1.25m each	MR
b	Basement	1.5m/0.75m	1.25m each	MR
C	Protection of exits			
a	Fire check door	N/A	N/A	N/A
b	Pressurization	N/A	N/A	N/A
D	No. of continuous staircases to terrace	Required	01 No.	MR
E	Width of corridor	1.5 m	Provided	MR
F	Door size	1.0 m	1.2 m	MR
3	Compartmentation:			
A	Fire check door	NA	NA	NA
B	Sealing of electrical shafts	N/A	N/A	N/A
C	Fire rating of shaft door	N/A	N/A	N/A
D	Water curtain	N/A	N/A	N/A
E	Fire dampers	N/A	N/A	N/A
4	Smoke Management System:			
A	Basement	30 ACPH	Exhaust fan	MR
B	Upper floor	12 ACPH	N/A	N/A


(e)

5. Fire Extinguisher:				
A	Total numbers	22 No's.	22 No's.	MR
B	Types	CO ₂ & ABC	CO ₂ & ABC	MR
C	ISI marking	ISI mark	Provided	MR
6 First-Aid-Hose Reel:				
A	Total numbers of each floor	02 nos at each floor	Provided	MR
B	Length of hose reel hose	30 m	Provided	MR
C	Nozzle diameter	05 mm	Provided	MR
7 Automatic Fire Detection and Alarming System:				
A	Type of detectors	N/A	N/A	N/A
B	Location of main panel	N/A	N/A	N/A
C	Location of repeater panel	N/A	N/A	N/A
D	Alternate source of power	N/A	N/A	N/A
E	Hooters	N/A	N/A	N/A
8	MOEFA:	N/A	N/A	N/A
9	Public Address System:	N/A	N/A	N/A
10 Automatic Sprinkler System:				
A	Basement	Required	Provided	MR
B	Upper floor	N/A	N/A	N/A
C	Sprinkler above false ceiling	N/A	N/A	N/A
11 Internal Hydrants:				
A	Size of riser/ down-comer	N/A	N/A	N/A
B	Number of hydrants per floor	N/A	N/A	N/A
C	Hose box	N/A	N/A	N/A
12 Yard Hydrants:				
A	Total number of hydrants	N/A	N/A	N/A
B	Hose box	N/A	N/A	N/A
13 Pumping Arrangements:				
1 Ground level				
A	Discharge of main pump	N/A	N/A	N/A
B	Head of main pump	N/A	N/A	N/A
C	Number of main pumps	N/A	N/A	N/A
D	Jockey pump out put	N/A	N/A	N/A
E	Jockey pump head	N/A	N/A	N/A
F	Standby pump out put	N/A	N/A	N/A
G	Standby pump head	N/A	N/A	N/A
H	Auto starting /manual stopping	N/A	N/A	N/A
I	Pump house access	N/A	N/A	N/A
2 Terrace Level				
A	Discharge of pump	900 & 180 LPM	Provided	MR
B	Head of the pump	40 m	Provided	MR
C	Power supply	Required	Provided	MR
D	Auto starting of pump	Required	Provided	MR
14 Captive Water Storage for Fire Fighting:				
A	Underground tank capacity	N/A	N/A	N/A
B	Draw-off connection	N/A	N/A	N/A
C	Fire service inlet	N/A	N/A	N/A
D	Access to tank	N/A	N/A	N/A
E	Overhead tank capacity	15,000 liters.	15,000 liters.	MR

15 Exit Signage:		Required	Provided	MR
16 Provision of Lifts:				
A	Pressurization of lift shaft	N/A	N/A	N/A
B	Pressurization of lift lobby	N/A	N/A	N/A
C	Communication in lift car	N/A	N/A	N/A
D	Firemen's grounding switch	N/A	N/A	N/A
E	Lift signage	N/A	N/A	N/A
17 Standby Power Supply:		N/A	N/A	N/A
18 Refuge Area:				
A	Total area	N/A	N/A	N/A
B	Location	N/A	N/A	N/A
19 Fire Control Room:				
A	Detector system panel	N/A	N/A	N/A
B	Flow switch panel	N/A	N/A	N/A
C	PA system panel	N/A	N/A	N/A
D	Battery backup	N/A	N/A	N/A
E	Building floor plans	N/A	N/A	N/A
20 Special Fire Protection systems for protection of special Risks, if any:		N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections. The shortcoming issued vide letter No F6/DFS/MS/2025/SZ/School/756 dated 26/09/2025 has been rectified.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter F6/DFS/MS/School/SZ/2022/906 dated 18/08/2022, renewal under Rule 37 of the Delhi Fire Service rules 2010, is recommended.



9/12/2025

Signature of the Inspecting Officer
Name Yashwant Singh Meena
Designation ADO/Mathura Road


D.O/SD



11/12/25


~~Dy. Insp.~~


12/12/25

A.K. MALIK
Principal Director

my. CFO to Sd/-



15/12/25
A.K. MALIK

D.O/SD

15/12/25