




Dated: 13/02/2026

No. F6/DFS/MS/EH/SZ/2026/146

**FIRE SAFETY CERTIFICATE**

Certified that the M/s ITP Laidback Café (Unit of World of Shalom Restaurant Private Limited) located at 1<sup>st</sup>, 2<sup>nd</sup>, 3<sup>rd</sup>, floors, M – 51, M – Block Market, Greater Kailash – II, New Delhi – 110048 in a building comprised of Basement (not part of rest.), Ground plus three upper floors, owned/occupied by Unit of World of Shalom Restaurant Private Limited was earlier Fire Safety Certificate issued from this department vide letter No. F6/DFS/MS/EH/2023/SZ/381 dated 29/12/2023. The said premises was re-inspected by the officer concerned of this department on 05/02/2026 in presence of Mr. Dhiraj Arora (Owner) and found that the fire premises / building have deemed complied with the prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule 2010 and that the premises / building is fit for occupancy class Group D “**Assembly Building**” (Restaurant running on 1<sup>st</sup>, 2<sup>nd</sup>, 3<sup>rd</sup>, floors only) with effect from 13/02/2026 for a period of **three years** in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010, printed below.

Issued on 13/02/2026 at New Delhi by.

  
A.K. Malik  
Dy. Chief Fire Officer  
Delhi Fire Service  
e/c (u)

**Copy to: -**

1. The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi - 110016 (Ref. MHA Application No. 2026012800936 dated 28/01/2026)
2. The Owner, M/s ITP Laidback Café (Unit of World of Shalom Restaurant Private Limited) located at 1<sup>st</sup>, 2<sup>nd</sup>, 3<sup>rd</sup>, floors, M – 51, M – Block Market, Greater Kailash – II, New Delhi – 110048.

**Condition for the validity of fire safety certificate**

1. All the means of escape shall be kept free of all the type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
5. Basement shall be used as per NBC/UBBL.
6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
7. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in).

## INSPECTION REPORT

1	Name & address of the building	M/s ITP Laidback Café (Unit of World of Shalom Restaurant Private Limited located at 1 <sup>st</sup> , 2 <sup>nd</sup> , 3 <sup>rd</sup> , floors, M – 51, M – Block Market, Greater Kailash – II, New Delhi – 110048.		
2	Building is comprised of	Basement, Ground plus three upper floors (Restaurant running on 1 <sup>st</sup> , 2 <sup>nd</sup> , 3 <sup>rd</sup> , floor only)		
3	Type of occupancy	Assembly "Group - D" (Restaurant)		
4	Type of case	Renewal Case		
5	Details of previous FSC	F6/DFS/MS/EH/2023/SZ/381 dated 29/12/2023		
6	Fire safety directives letter no.	Cir. No. F6/DFS/EH/SZ/MS/2005/718 dated 04/04/2005		
7	Date of inspection	05.02.2026		
8	Name of the inspecting officers	Yashwant Singh Meena, ADO/ M. Road		
9	Name of the designation of officer from the building side	Mr. Dhiraj Arora (Owner)		
10	Year of construction	1999	Restaurant running on 1 <sup>st</sup> , 2 <sup>nd</sup> , 3 <sup>rd</sup> , floor only	
11	Applicant's letter no.	Application No. 2026012800936 dated 28/01/2026		
S.No	Minimum standard of fire prevention and fire safety U/R 33	Cir. No. 718 dt 04/04/2005	Provided at site	Remarks MR/NMR
<b>1</b>	<b>Access to Building:</b>			
	<b>A</b> Road width	Required	9.0 meters	MR
	<b>B</b> Gate width	N/A	N/A	N/A
	<b>C</b> Width of internal road	N/A	N/A	N/A
<b>2</b>	<b>Number, Width, Type and Arrangement of Exits:</b>			
	<b>A</b> Number of staircases			
	a Upper floor	02 Nos	02 Nos	MR
	c Basement	N/A	Not part of restt.	N/A
	<b>B</b> Width of staircases			
	a Upper floor	1.15 m & 1.25 m	1.15 m & 1.25 m	MR (Old Case)
	b Basement	N/A	N/A	N/A
	<b>C</b> Protection of exits			
	a Fire check door	N/A	N/A	N/A
	b Pressurization	N/A	N/A	N/A
	<b>D</b> No. of continuous staircases to terrace	Required	One	MR
	<b>E</b> Width of corridor	N/A	N/A	N/A
	<b>F</b> Door size	1.0 meter	1.0 meter. (02 nos.)	MR (Old Case)
<b>3</b>	<b>Compartmentation:</b>			
	<b>A</b> Fire check door	N/A	N/A	N/A
	<b>B</b> Sealing of electrical shafts	N/A	N/A	N/A
	<b>C</b> Fire rating of shaft door	N/A	N/A	N/A
	<b>D</b> Water curtain	N/A	N/A	N/A
	<b>E</b> Fire dampers	N/A	N/A	N/A
<b>4</b>	<b>Smoke Management System:</b>			
	<b>A</b> Basement	N/A	N/A	N/A
	<b>B</b> Upper floor	Required	Exhaust fan Provided	MR

2/18

<b>5. Fire Extinguisher:</b>				
A	Total numbers	10 nos.	10 nos.	MR
B	Types	CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	MR
C	ISI marking	ISI Marked	Provided	MR
<b>6 First-Aid-Hose Reel:</b>				
A	Total numbers of each floor	01 no	01 no	MR
B	Length of hose reel hose	30 m	30 m	MR
C	Nozzle diameter	05 mm	05 mm	MR
<b>7 Automatic Fire Detection and Alarming System:</b>				
A	Type of detectors	N/A	N/A	N/A
B	Location of main panel	N/A	N/A	N/A
C	Location of repeater panel	N/A	N/A	N/A
D	Alternate source of power	N/A	N/A	N/A
E	Hooters	N/A	N/A	N/A
<b>8 MOEFA:</b>		Required	Provided	MR
<b>9 Public Address System:</b>		N/A	N/A	N/A
<b>10 Automatic Sprinkler System:</b>				
A	Basement	N/A	N/A	N/A
B	Upper floor	Required	Provided	MR
C	Sprinkler above false ceiling	N/A	N/A	N/A
<b>11 Internal Hydrants:</b>				
A	Size of riser/down-comer	100 mm	100 mm	MR
B	Number of hydrants per Branch	01 no.	01 no.	MR
C	Hose box	01 no.	01 no.	MR
<b>12 Yard Hydrants:</b>				
A	Total number of hydrants	N/A	N/A	N/A
B	Hose box	N/A	N/A	N/A
<b>13 Pumping Arrangements:</b>				
<b>1 Ground level</b>				
A	Discharge of main pump	N/A	N/A	N/A
B	Head of main pump	N/A	N/A	N/A
C	Number of main pumps	N/A	N/A	N/A
D	Jockey pump out put	N/A	N/A	N/A
E	Jockey pump head	N/A	N/A	N/A
F	Standby pump out put	N/A	N/A	N/A
G	Standby pump head	N/A	N/A	N/A
H	Auto starting /manual stopping	N/A	N/A	N/A
<b>2 Terrace Level</b>				
A	Discharge of pump	225 & 180 LPM	450 LPM x 02 no.	MR
B	Head of the pump	40 m	40 m	MR
C	Power supply	Required	Provided	MR
D	Auto starting of pump	Required	Provided	MR

u

<b>14 Fire Fighting:</b>				
A	Underground tank capacity	N/A	N/A	N/A
B	Draw-off connection	N/A	N/A	N/A
C	Fire service inlet	N/A	N/A	N/A
D	Access to tank	N/A	N/A	N/A
E	Overhead tank capacity	5,000 liters	10,000 liters	N/A
15	<b>Exit Signage:</b>	Required	Provided	MR
16	<b>Provision of Lifts:</b>			MR
A	Pressurization of lift shaft	N/A	N/A	N/A
B	Pressurization of lift lobby	N/A	N/A	N/A
C	Communication in lift car	N/A	N/A	N/A
D	Firemen's grounding switch	N/A	N/A	N/A
E	Lift signage	N/A	N/A	N/A
17	<b>Standby Power Supply:</b>	Required	Provided	MR
18	<b>Refuge Area:</b>			
A	Total area	N/A	N/A	N/A
B	Location	N/A	N/A	N/A
19	<b>Fire Control Room:</b>			
A	Detector system panel	N/A	N/A	N/A
B	Flow switch panel	N/A	N/A	N/A
C	PA system panel	N/A	N/A	N/A
D	Battery backup	N/A	N/A	N/A
E	Building floor plans	N/A	N/A	N/A
20	<b>Special Fire Protection systems for protection of special Risks, if</b>			N/A

The fire protection system was randomly checked and tested and was found functional at the time of inspection.

Keeping in view the compliance of the minimum standards of fire prevention and safety measures as required under the rules. The Fire Safety Certificate issued vide letter F6/DFS/MS/EH/2023/SZ/381 dated 29/12/2023 renewal under rule 37 of the Delhi Service rules 2010 is recommended. (last date 26/2/2026)

Signature of the Inspecting Of  
 Name: Yashwant Singh M  
 Designation: ADO /Mathura F

D.O/SD

*[Signature]*  
 9/2/24

*[Signature]*  
 12/2/24

*[Signature]*  
 10/2/26

**A. K. MALIK**  
 Principal Director

*[Signature]*  
 12/2/26  
**A.K. MALIK**

*[Signature]*  
 My. CEO (or)

My. CEO to Inspect  
*[Signature]*  
 11/2/26