

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

C/74

No.F.6/DFS/MS/NDZ/2025/ 54

Dated: 06/02/2025

To,

Sh. Pradeep Kumar Mishra,
Administrative Officer (OA),
Ministry of External Affairs,
New Delhi.

Sub: - Regarding of fire safety certificate in r/o Jawahar Lal Nehru Bhawan, New Delhi.
Sir,

This has a reference to mail id <aoestt@mea.gov.in> dated 06.01.2025, on the subject cited above. In this connection, it is to inform you that the premise was inspected by the officers concerned of this department on 24/01/25 in the presence of Sh. Sandeep and observed that the following shortcomings

1. Fire check door glass found broken in basement and door closers found removed at some places.
2. Pressurization of staircases & lift shaft found nonfunctional and not integrated with fire detection system.
3. Electric shaft are not sealed.
4. Smoke management system in basement found nonfunctional and also not integrated with detection system.
5. In basement sprinkler are hidden above ventilation shaft, required to be lowered below ducting.
6. Exit Signage found inadequate in basement.
7. Diesel Engine pump found nonfunctional.
8. Further, temporary rooms /partitions have been made in basement and firefighting system such as detection system , sprinklers is not extended to that area and use of some portion of basement has been changed to residential (barrack) , Accordingly approval from NDMC is required.

In view of above case is rejected with a request to rectify the above shortcomings at the earliest for further consideration in the matter.

Yours faithfully

(Atul Garg)
DIRECTOR
Delhi Fire Service

Copy to:

1. The Chairman, NDMC, Palika Kendra, New Delhi.