



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

dist/DFSA
आजादी का
अमृत महोत्सव

DFA + F1

No. F6/DFS/MS/School/2025/NDZ/ 430

Dated: 21/05/2025

To,

The Principal,
MCD Primary School
Harizan Basti, E – Block,
East Gokalpur, Delhi – 110094.

**Sub.: - Inspection Report in r/o MCD Primary School located at Harizan Basti, E – Block,
East Gokalpur, Delhi – 110094.**

Sir,

Please refer to your outdoor diary No. 792 dated 21/04/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 14/05/2024 and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/School/2022/NDZ/304 dated 10/06/2022 (copy enclosed).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Enclosed: As above

(ATUL GARG)
DIRECTOR

O/c DELHI FIRE SERVICE

Copy to: -

1. The Dy. Director of Education, Municipal Corporation of Delhi, Plot No.419, Patparganj Industrial Area, Delhi - 110092.
2. The Executive Engineer (Elect,) – II, Shahdara, MCD Zonal Office Building, Keshav Chowk, G.T Road, Nera Shyam Lal Collage, Delhi.

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**

No. F6/DFS/MS/School/2022/NDZ/304

Dated 10/06/2022

To,

The Principal,
EDMC Primary School,
Harizan Basti, E-Block,
East Gokalpur, Delhi-110094.

Sub:- Regarding Issuance Fire Safety Certificate in r/o EDMC Primary School at Harizan Basti, E-Block, East Gokalpur, Delhi-110094.

Sir,

With reference to your letter No. EDMC/EE(E)-I/SHN/2021-22/D-40 dated-02/05/2022 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned school from fire safety point of view on dated 31/05/22 in presence of Mr. Vijay Pal Principal. The following points / shortcomings were noticed in the building which is comprised of ground plus two upper floors .

1. First Aid Hose Reels not functional.
2. A fire pump having 450 LPM output at 40 meters head not functional.
3. Over head tank 8,000 liter provided in place of 10,000 liter as required

In view of above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully



(Dr. S.K Tomar)
Dy. Cheif Fire Officer



Copy to:-

1. The Director of Education, EDMC
Udyog Sadan, Plot No. 419, FIE,
Patparganj, Delhi 92
2. The Ex. Eng. (Elect.)-II,
Shahdara (North)Zone,
EDMC, Office of Executive Engineer (Elect)-II,
MCD Zonal Office Buildings, Keshav Chowk,
G.T. Road, Near Shyam Lal College.