



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

7/5
आज़ादी का
अमृत महोत्सव

No.F6/DFS/MS/School/2025/NDZ/261

Dated: 22/04/2025

To,

The Principal,
M.C.P.S. (Girls),
Kondli No.1(I), Kondli Village,
Delhi-110096.

Subject: - Regarding Renewal of FSC in r/o M.C.P.S. (Girls), Kondli No. 1 (I) Kondli Village, Delhi - 110096.

Sir,

Please refer to your Outdoor Dairy No.145 dated 03/04/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 09/04/2025 and observed that the shortcomings issued by this department vide letter no. F6/DFS/MS/School/NDZ/2024/44 dated 08/02/2024 (copy enclosed) have still not complied.

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Enclosed: as above

Yours faithfully,

(ATUL GARG)
DIRECTOR

o/c DELHI FIRE SERVICE

Copy to: -

1. The Director of Education, MCD Civic Centre, Jawahar Lal Nehru Marg, New Delhi - 110002.



Dated: 08/02/2024

DFS/MS/School/NDZ/2024/44

To,

The Principal,
MCD Primary School No.01,
Kondli Village, Delhi-110096.

Sub: - Regarding grant of Fire Safety Certificate in r/o MCD Primary School No.01, located at, Kondli Village, Delhi-110096

Sir,

This has a reference to your Email dated - 20.11.2023, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 30/01/2024 in the presence of Mrs. Santoshi Gudiya (Principal) and observed that building comprised of ground plus two upper floors only and following shortcomings were observed during time of inspection:

1. Fire Extinguisher not provided.
2. First-Aid-Hose Reel not provided.
3. MOEFA not provided
4. Fire pump of 450 LPM not provided.
5. Overhead tank capacity 10,000 liters not provided.
6. Exit Signage's not provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to:-

1. The Principal, MCD Primary School No.01, located at, Kondli Village, Delhi-110096.
2. The Director of Education, MCD, Udyod Sadan, Plot no.419, FIE, Patparganj Industrial Area, Delhi-110092.