

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE  
NEW DELHI-110001**

No.F6/DFS/MS/EH/2025/SZ/ 100

Dated..19/03/2025

**FIRE SAFETY CERTIFICATE**

Certified that M/s New Minar Restaurant, located at M-65, Ground, First & Second Floor, M-Block Market, GK-1, New Delhi 110048 comprised of ground & 02 upper floors was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/EH/2022/SZ/222 dated 04.08.2022. The restaurant premise was inspected by the officer concerned of this department on 08.03.2025 in the presence of Mr. Lalit Kr. Chopra (Owner) and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" (Restaurant at GF, FF & SF only) with effect from 19/03/2025 and valid upto 31.03.2028, in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 19/03/2025 at New Delhi by

(ATUL GARG)  
DIRECTOR  
DELHI FIRE SERVICE

Copy to: -

1. The Commissioner, North, MCD, Civic Centre, New Delhi
2. The Addl. Commissioner of Police Lic/Branch, 1<sup>st</sup> Floor PS Defence Colony, New Delhi 110049, Online ID No- 2025022702521 dated 27.02.2025
3. M/s New Minar Restaurant, located at M-65, Ground, First & Second Floor, M-Block Market, GK-1, New Delhi 110048.

**Conditions for the validity of Fire Safety Certificate: -**

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the MHA portal along with a copy of this Certificate, **six months** prior to its expiry".

## INSPECTION REPORT

1	Name & Address of the Building	M/s New Minar Restaurant, located at M-65, Ground, First & Second Floor, M-Block Market, GK-1, New Delhi 110048		
2	Type of Occupancy	Group-D Assembly Building. (Eating House)		
3	Building Comprised of	Ground plus Two upper floors		
4	Type of Case	Renewal		
5	Details of Previous NOC	F6/DFS/MS/EH/2022/SZ/222 dated 04.08.2022		
6	Fire Safety Directives Letter No	Nil		
7	Date of Inspection	08.03.2025		
8	Name of the Inspecting Officers	ADO (RN)		
9	Name & Designation of Officers from the building side	Mr. Lalit Kr. Chopra (Owner)		
10	Year of construction	2005	Restt. Running at GF, 1 <sup>st</sup> & 2 <sup>nd</sup> Floor.	
11	Applicant letter No.	MHA Portal 2025022702521 dated 27.02.2025		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC requirements	Provided at Site	Remarks MR/NMR
1	<b>Access to Building.</b>			
	• Road width	09 mtr	4.5 m	MR (old Case)
	• Gate width	N/A	N/A	N/A
	• Width of internal road	N/A	N/A	N/A
2	<b>Number, width, type &amp; arrangement of exits.</b>			
	<b>a) Number of Staircase</b>			
	➤ Upper floors.	02	02	MR
	➤ Basement floor.	N/A	N/A	N/A
	<b>b) Width of Staircase</b>			
	➤ Upper floors	1.25 mtr	1.11m & 0.72m	MR (being old case)
	➤ Basement floor	N/A	N/A	N/A
	<b>c) Protection of exits</b>			
	➤ Fire check door	N/A	N/A	N/A
	➤ Pressurization	N/A	N/A	N/A
	<b>d) No. of continuous staircase to terrace</b>	Required	Provided	MR
	<b>e) Width of corridor</b>	N/A	N/A	N/A
	<b>f) Door size</b>	02 Exits, 1.50 m	1.5m & 1 m	MR (being old case)
3	<b>Compartmentation.</b>			
	• Fire check door.	N/A	N/A	N/A
	• Sealing of electrical shafts.	N/A	N/A	N/A
	• Fire rating of shaft door.	N/A	N/A	N/A
	• Water curtain	N/A	N/A	N/A
	• Fire dampers.	N/A	N/A	N/A
4	<b>Smoke Management system.</b>			
	• Basement	NA	N/A	N/A
	• Upper floors	Required	Exhaust Fans Provided	MR
5	<b>Fire Extinguishers.</b>			
	• Total numbers	06 Nos	08 Nos	MR
	• Types	ABC/CO <sub>2</sub>	ABC-04 & CO <sub>2</sub> -02	MR
	• ISI Marking	ISI marked	Provided	MR
6	<b>First Aid Hose Reels.</b>			
	• Total numbers on each floor.	One	Provided	MR
	• Length of hose-reel hose.	30m	Provided	MR
	• Nozzle Diameter	5mm	Provided	MR
7	<b>Automatic fire detection &amp; alarming system.</b>			
	• Type of detectors	N/A	N/A	N/A
	• Location of Main Panel	N/A	N/A	N/A




N/A  
N/A  
N/A  
N/A




N/24

20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A
----	--	-----	-----	-----


The fire protection system provided in the building were randomly checked and found functional at the time of inspection.


Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2022/SZ/222 dated 04.08.2022, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

  
Signature of the Inspecting Officer  
Name: C.L. Meena  
Designation: ADO (RN)

DO (South)   
  
  
11/31/2025  
Director

As approved, F.T. letter is setup for your signature please.

Director (DFS) 

  
17/03/2025  
ADO (RN)

Uploaded  
19/03/25  
