

 **GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

C-11



No: F.6/DFS/MS/2026/WZ/172

Dated: 25/02/26

To,

The Principal,  
Nigam Pratibha Bal Vidyalaya  
Nangloi, Saidan-II, Ambika Vihar,  
Paschim Vihar, Delhi.

Sub:- Regarding issuance of Fire Safety Certificate in respect of Nigam Pratibha Bal Vidyalaya located at Nangloi, Saidan-II, Ambika Vihar, Paschim Vihar, Delhi.

Sir,


This has reference to your e mail id dated 02/02/2026 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 06.02.2026 to see the compliance of the requisite fire safety measures. Sh. Nand Kishor Narayan was present at the time of inspection.

During the course of inspection it was observed school building is comprised of 2 Blocks – Block-1 (G+1) & Block-2 (G+2). Your request for issuance of FSC is rejected as the following shortcomings were observed:-

1. First aid hose reels found provided but not functional.
2. Terrace level pump found provided but not functional and also not connected to Over Head Tank.
3. Overhead tank of 5000 ltrs capacity found provided against the required capacity of 10,000 ltrs.

You are advised to rectify the above-mentioned shortcoming for taking further action as necessary for issuance of Fire Safety Certificate. Till such time the occupancy of the building is at the risk and responsibility of owner/ occupier.

Yours Faithfully

  
24/02/26  
(S.K. Dua)

Dy. Chief Fire Officer (WZ)  
Delhi Fire Service



Copy to :-

1. Director of Education, MCD, Civic Centre, Delhi.