

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

75  
आजादी का  
अमृत महोत्सव

No. F6/DFS/MS/WZ/2025/BNQT/ 59

Dated:- 09/12/2025

**FIRE SAFETY CERTIFICATE**

Certified that the M/s Nimantran Dil Se, located at Hall No. 201, 2<sup>nd</sup> Floor, N.N. Mall, Near M2K, Manglam Place, Sector-3, Rohini, Delhi-110085, Banquet Hall is running at 2<sup>nd</sup> Floor in a building is comprised of Double Basement + Ground + 05 Upper Floors only, was issued Fire Safety Certificate by this department Vide Letter No. F6/DFS/MS/2022/WZ/EH/BNQT./60 Dated 27/10/2025. The said premise was re-inspected by the officer concerned of this department on 29/11/2025 in the presence of Sh. Deepak Bubber (Owner) and found that the premises/building have deemed complied with the fire prevention and fire safety requirements in accordance with the Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises/building is fit for occupancy class "Assembly" Group D for Banquet Hall is running at 2<sup>nd</sup> Floor (Hall No. 201) with effect from 09/12/2025 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued on 09/12/2025 at New Delhi by

*S.K. Dua*  
09/12/25

Dy. Chief Fire Officer (WZ)  
Delhi Fire Service

Copy to:-

1. The Commissioner, Municipal Corporation of Delhi, Civic Centre, Minto Road, New Delhi-110002:- in r/o computer id no. 202511114735 dated 11/11/2025.
2. The Authorized Signatory, M/s Nimantran Dil Se, located at Hall No. 201, 2<sup>nd</sup> Floor, N.N. Mall, Near M2K, Manglam Place, Sector-3, Rohini, Delhi-110085.

**Conditions for the validity of Fire Safety Certificate:-**

1. All the means of escape shall be kept free of all type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
6. All comments / directions of licensing Department shall always be permitted and followed.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

N/10 -  
**INSPECTION REPORT**

1. Name & address of the building : M/s. Nimantran Dil Se, located at Hall No. 201, 2<sup>nd</sup> Floor, N.N. Mall, Near M2K, Manglam Place, Sector-3, Rohini, Delhi-110085
2. Type of Occupancy : Assembly, (Banquet Hall is running at 2<sup>nd</sup> floor)
3. Type of Case : Renewal
4. Details of previous NOC : F6/DFS/MS/2020/WZ/EH/BNQT/60 dated 27/10/2022
5. Fire Safety directives Letter No. : NBC (Part-IV)
6. Date of inspection : 29/11/2025
7. Name of the Inspecting Officer : Aman Kumar Lathar, ADO (BW/RN)
8. Name and designation of Officer from the building side : Sh. Deepak Bubbar (Owner)
9. Year of Construction : 2000
10. Applicant's online id no. : 202511114735 dated 11/11/2025  
The banquet hall is running at 2<sup>nd</sup> floor within N.N. Mall building comprised of basement, ground plus 05 upper floors.

S No	Minimum standards on fire prevention and fire safety U/R 33	UBBL/NBC Requirements	Provided at site	Remarks MR/N MR
1.	Access of building [N.N. Mall, Manglam Place District Centre issued FSC vide letter no. F.6/DFS/MS/2025/WZ/577 dated 29/10/2025			
	• Road width	09 m	09 m	MR
	• Gate width	05 m	Directly Accessible	MR
	• Width of internal road	NA	NA	NA
2.	Number, width, Type & Arrangements-of exits			
	a. Number of staircases	02 nos.	02 nos.	MR
	• Upper floors	NA	NA	NA
	• Basements			
	b. Width of staircases	1.5 m x 2	Provided	MR
	• Upper floors	NA	NA	NA
	• Basements			
	c. Protection of exits	NA	NA	NA
	• Fire check door	Required	Provided	MR
	• Pressurization	02 nos.	02 nos.	MR
	d. No of continuous staircase to terrace	NA	NA	NA
	e. Width Of Corridor	2.0 m & 1.50 m	Provided	MR
	f. Door Size			
3.	Compartmentation			
	• Fire check door	NA	NA	NA
	• Sealing of electrical shafts	Required	Provided	MR
	• Fire Rating of shaft door	Required	Provided	MR
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4.	Smoke managements System			
	• Basements	NA	NA	NA
	• Upper floors	12 a/c per hour	Exhaust fan	MR
5.	Fire Extinguishers			
	• Total numbers	One "300 m <sup>2</sup> "	07 nos.	MR
	• Types	ABC & CO <sub>2</sub>	Provided	MR
	• IS marking	ISI marked	Provided	MR
6.	First - Aid Hose Reels			
	• Total numbers on each floor	01 near to banquet	Provided (2 nos.)	MR
	• Length of hose reel hose	30 m	Provided	MR
	• Nozzle diameter	05 mm	Provided	MR

7.	Automatic fire detection and alarming system			
	• Type of detectors	Smoke/Heat	Provided	MR
	• Location of Main Panel	Required	Provided	MR
	• Location of Repeater Panel	Required	Provided	MR
	• Alternate source of power	Required	Provided	MR
	• Hooters' Location	Required	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System	[Provided & Maintained by Mall Management]		
	• Basements	Required	Provided	MR
	• Upper Floor	Required	Provided	MR
	• Sprinkler above false ceiling	Required	Provided	MR
11.	Internal Hydrants	[Provided & Maintained by Mall Management]		
	• Size of riser/down- comer	150 mm	Provided	MR
	• Number of hydrants per floor	01 (near to banquet)	Provided (02 nos.)	MR
	• Hose Box	01 (near to banquet)	Provided (02 nos.)	MR
12.	Yard Hydrants	[Provided & Maintained by Mall Management]		
	• Total number of hydrants	NA	Provided	NA
	• Hose Box	NA	Provided	NA
13.	Pumping Arrangements	[Provided & Maintained by Mall Management]		
	• Ground Level			
	• Discharge of main pump	2280 lpm	Provided	MR
	➤ Head of main pump	60 m	Provided	MR
	➤ Number of main pumps	02 nos.	Provided	MR
	➤ Jockey pump out put	180 lpm	Provided	MR
	➤ Jockey pump head	60 m	Provided	MR
	➤ Standby Pump out put	2280 lpm	Provided	MR
	➤ Standby Pump Head	80 m	Provided	MR
	➤ Auto Staring/Manual stopping	Required	Provided	MR
	➤ Pump House Access	Required	Provided	MR
	• Terrace level			
	➤ Discharge of pump	02 nos. of 450 lpm	Provided	MR
	➤ Head of the pump	40 m	Provided	MR
	➤ Power supply	Required	Provided	MR
	➤ Auto starting of pump	Required	Provided	MR
14.	Captive water Storage for fire fighting	[Provided & Maintained by Mall Management]		
	• Under ground tank capacity	1,00,000 ltrs.	2,00,000 ltrs.	MR
	➤ Draw off connection	Required	Provided	MR
	➤ Fire service inlet	Required	Provided	MR
	➤ Access to tank	Required	Provided	MR
	• Overhead Tank capacity	10,000 ltrs.	30,000 ltrs.	MR
15.	Exit Signage	Required	Provided	MR
16.	Provision of Lifts	[Provided & Maintained by Mall Management]		
	➤ Pressurization of Lift Shaft	Required	Provided	MR
	➤ Pressurization of lift lobby	NA	NA	NA
	➤ Communication in lift Car	Required	Provided	MR
	➤ Fireman's Grounding Switch	Required	Provided	MR
	➤ Lift Signage	Required	Provided	MR
17.	Standby power supply	NA	NA	NA
18.	Refuge Area			
	➤ Total area	NA	NA	NA
	➤ Location	NA	NA	NA
19.	Fire control room			
	➤ Detector system panel	NA	NA	NA
	➤ Flow Switch Panel	NA	NA	NA
	➤ PA System Panel	NA	NA	NA
	➤ Battery backup	NA	NA	NA
	➤ Building Floor Plans	NA	NA	NA
20.	Special Fire Protection Systems for Protection of special Risks, if any;	NA	NA	NA

*Qu.*

N<sup>o</sup> 12 -

The fire protection systems provided in the building were checked and found functional at the time of inspection. This shortcoming issued vide letter no. F.6/DFS/MS/Bnqt/SZ/2025/64 dated 22/04/2025 found rectified.

In view of the deemed compliance of minimum standards on fire prevention and fire safety requirements under the rules, renewal of Fire Safety Certificate issued vide letter no. F6/DFS/MS/2020/WZ/EH/BNQT/60 dated 27/10/2022 is **recommended** under rule 37 of the Delhi Fire Service Rule, 2010 under DFS Act 2007.

Accordingly DFA is prepared & put up for approval please.

*[Signature]*  
Aman Kumar Lathar  
ADO (BW/RN)

~~DO/MS~~ Approved  
4/12/2025  
By CFO (WZ)

~~Pr. Director~~ *[Signature]*  
CFO to *[Signature]*

~~By CFO (WZ)~~ *[Signature]*  
F.T. pl.

ADO (BW/RN)

F.T. letter is added for your signature pl.

~~FO (BZ)~~ *[Signature]*

F.P. wing

Uploaded C fire

*[Signature]*  
02/12/25