



No F.6/DFS/MS/2025/School/WZ/1309

Dated 12/11/2025

**FIRE SAFETY CERTIFICATE**

Certified that the Brahma Shakti Public School located at E-Block, Bharat Vihar, Begumpur (Opposite Sector-22 & 23), Rohini, Delhi-110086, comprised of Ground & 02 upper floors was issued Fire Safety Certificated vide this office letter no. F6/DFS/MS/2022/WZ/School/991 dated 09/09/2022. The premises was inspected by the officer concerned of this department on 30/10/2025 in the presence of Mr. Satender Kumar (Manager) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class "Group B Educational (School)" with effect from 12/11/2025 for a period of three years, in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ....12/11/2025 at New Delhi by

  
 (S.K. Dua)

Dy. Chief Fire Officer  
 Delhi Fire Service

Copy to :-

1. The Dy. Director of Education, Zone- XIII, District North West- B (II), Sector-9, Rohini, Delhi - 110085.
2. The Manager, Brahma Shakti Public School located at E-Block, Bharat Vihar, Begumpur (Opposite Sector-22 & 23), Rohini, Delhi-110086.

**Conditions for the validity of Fire Safety Certificate:**

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
4. All the staff members must know the correct method of operation of firefighting system.
5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <http://delhi.gov.in./wps/wcm/connect/doi/fire/FIRE/Home/Forms>.
6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

11/24

**INSPECTION REPORT**

1. Name & address of the building : Brahma Shakti Public School, E-Block, Bharat Vihar, Begumpur (Opposite Sector-22 & 23), Rohini, Delhi-86.
2. Type of Occupancy : Educational
3. Type of Case : Renewal
4. Composition of building : Ground & 02 upper floors
5. Details of Previous NOC : F6/DFS/MS/2022/WZ/School/991 dated 09/09/2022.
6. Fire Safety directives letter No : Nil
7. Date of inspection : 30/10/2025
8. Name of Inspecting Officer : ADO (Rohini)
9. Name and designation of officers  
From the building side : Mr. Satender Kumar (Manager)
10. Year of Construction : 2004
11. Applicant's letter No. : Online e-mail dated 29/09/2025

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Part-IV Requirements	Provided at site	Remarks MR/NMR
1.	<b>Access to building</b>			
	<ul style="list-style-type: none"> <li>• Road width</li> <li>• Gate width</li> <li>• Width of internal road</li> </ul>	Accessible	Accessible	MR
		Directly Accessible	Directly Accessible	MR
		NA	NA	NA
2.	<b>Number, Width, Type &amp; Arrangement of Exits</b>			
	a. Number of staircases			
	• Upper Floors	02	02	MR
	• Basements	NA	NA	NA
	b. Width of staircases			
	• Upper Floor	1.50m	1.70m & 1.20m	MR (Old case)
	• Basements	NA	NA	NA
	c. Protection of exits			
	Fire check door	NA	NA	NA
	• Pressurization	NA	NA	NA
	d. No. of continuous staircases to terrace	01	01	MR
	e. Width of Corridor	NA	NA	NA
	f. Door Size	1.0m	1.0m	MR
3.	<b>Compartmentation</b>			
	• Fire check door	NA	NA	NA
	• Sealing of electrical shafts	NA	NA	NA
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4.	<b>Smoke Management System</b>			
	• Basements	NA	NA	NA
	• Upper floors	Required	Natural ventilation	MR
5.	<b>Fire Extinguishers</b>			
	• Total numbers	12nos.	Provided	MR
	• Types	ABC/CO2	Provided	MR
	• IS marking	ISI marked	Provided	MR
6.	<b>First-Aid Hose Reels</b>			
	• Total numbers on each floor	01	Provided	MR
	• Length of hose reel hose	30m	Provided	MR
	• Nozzle diameter	5m	Provided	MR

9 \* 3

7.	<b>Automatic fire detection and alarming system</b> 17/25			
	<ul style="list-style-type: none"> <li>Type of detectors</li> <li>Location of Main Panel</li> <li>Location of Repeater Panel</li> <li>Alternate source of power</li> <li>Hooters' Location</li> </ul>	NA	NA	NA
8.	<b>MOEFA</b>	NA	NA	NA
9.	<b>Public Address System</b>	NA	NA	NA
10.	<b>Automatic Sprinkler System</b>			
	<ul style="list-style-type: none"> <li>Basement</li> <li>Ground &amp; Upper Floors</li> <li>Sprinkler above false ceiling</li> </ul>	NA	NA	NA
11.	<b>Internal Hydrants</b>			
	<ul style="list-style-type: none"> <li>Size of riser/down-comer</li> <li>Number of hydrants per floor</li> <li>Hose Box</li> </ul>	NA	NA	NA
12.	<b>Yard Hydrants</b>			
	<ul style="list-style-type: none"> <li>Total number of hydrants</li> <li>Hose Box</li> </ul>	NA	NA	NA
13.	<b>Pumping Arrangements</b>			
	<ul style="list-style-type: none"> <li>Ground Level <ul style="list-style-type: none"> <li>Discharge of main Pump</li> <li>Head of Main pump</li> <li>Number of main pumps</li> <li>Jockey Pump out put</li> <li>Jockey pump head</li> <li>Standby Pump out put</li> <li>Standby Pump Head</li> <li>Auto Starting/Manual Stopping</li> <li>Pump House Access</li> </ul> </li> </ul>	NA	NA	NA
	<ul style="list-style-type: none"> <li>Terrace level <ul style="list-style-type: none"> <li>Discharge of pump</li> <li>Head of the pump</li> <li>Power Supply</li> <li>Auto Starting of pump</li> </ul> </li> </ul>	450 LPM	450 LPM	MR
		40m	40m	MR
		Required	Provided	MR
		Required	Provided	MR
14.	<b>Captive Water Storage for fire fighting</b>			
	<ul style="list-style-type: none"> <li>Underground tank capacity <ul style="list-style-type: none"> <li>Draw-off connection</li> <li>Fire service inlet</li> <li>Access to tank</li> </ul> </li> <li>Overhead Tank capacity</li> </ul>	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		10,000ltr	Provided	MR
15.	<b>Exit Signage.</b>	Required	Provided	MR
16.	<b>Provision of Lifts.</b>			
	<ul style="list-style-type: none"> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> </ul>	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
17.	<b>Standby power supply</b>	NA	NA	NA
18.	<b>Refuge Area.</b>			
	<ul style="list-style-type: none"> <li>Total Area</li> <li>Location</li> </ul>	NA	NA	NA
		NA	NA	NA

9 8

NA


N/26

**Fire Control Room**

• Detector System Panel • Flow Switch Panel • PA System Panel • Battery backup • Building Floor Plans	NA	NA	NA
	NA	NA	NA
	NA	NA	NA
	NA	NA	NA
	NA	NA	NA
20. Special Fire Protection System for Protection of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures. **It is recommended for renewal for fire safety certificate** as required under the rules, renewal of FSC issued vide this department letter of even no. F6/DFS/MS/2022/WZ/School/991 dated 09/09/2022 is recommended.

  
 Signature of the Inspecting Officer  
 Name :- C.L. Meena  
 Designation:- ADO (Rohini)

~~DOANW~~  
~~3.11.2025~~  
~~Dy CFO (WZ)~~  
~~Principal Director~~

~~Kirp~~  
~~03/11/25~~

~~Dy. CFO to Secy.~~

~~Dy. CFO (WZ)~~


~~04/11/25~~

F.T. please.

~~Kirp~~  
~~04/11/25~~

~~ADO (Rohini)~~

As approved, F.T. letter is kept up for your signature please.

  
 10/11/2025

~~Dy CFO (WZ)~~

~~Kirp~~  
~~10/11/25~~

~~F.P. Wing~~