



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001



No. F6/DFS/MS/2025/School/ 1197

Dated: 26/09/2025

FIRE SAFETY CERTIFICATE

Certified that the S.M.S. Public School located at A-61, Near Pili Kothi, Nathupura, Delhi-110084 comprised of Ground & 02 upper floors owned/ occupied by the S.M.S. Public School was issued fire safety certificate vide this office letter no. F6/DFS/MS/2020/WZ/27 dated 27/01/2020. The premises was inspected by the officer concerned of this department on 18/09/2025 in the presence of Sh. Lalit Kr. Tyagi (Chairman) and observed that all the fire prevention and fire safety arrangements as provided in the premise found in good working condition. The premise have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy class "Group B Educational (School)" with effect from 26/09/2025 for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010,

Issued on ... 26/09/2025 at New Delhi by


 Virendra Singh
 Chief Fire Officer
 Delhi Fire Service
 etc etc

Copy to:-

1. The Deputy Director of Education, GNCT of Delhi, Zone-VII, District North Lucknow Road, Timarpur, Delhi – 110054.
2. The Chairmen, S.M.S. Public School located at A-61, Near Pili Kothi, Nathupura, Burari, Delhi-110084.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
4. All the staff members must know the correct method of operation of firefighting system.
5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <http://delhi.gov.in/wps/wcm/connect/doi/fire/FIRE/Home/Forms>.
6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
8. This fire safety certificate is valid for ground & 02 upper floors only. In case of any violation, this FSC will be treated as null & void.

INSPECTION REPORT

1. Name & address of the building : S M S Public School at A/61, Near Pili Kothi, Nathupura, Delhi-84.
2. Type of Occupancy : Educational
3. Type of Case : Renewal
4. Composition of building : Ground & 02 upper floors and two store room on terrace
5. Details of previous NOC : F6/DFS/MS/2020/WZ/27 dated 27/01/2020
6. Fire Safety directives letter No : Nil
7. Date of inspection : 18/09/2025
8. Name of the Inspecting Officers : ADO (RN)
9. Name and designation of officers from the building side : Mr. Lalit Kr. Tyagi (Chairman)
10. Year of Construction : 2006/ 2015
11. Applicant's letter No. : Letter No- 1345/09/25/S.M.S.P.S dated: 10/09/2025

	Minimum Standards on fire prevention and fire safety U/R 33	Requirements as per Rules 35 (6)	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	Accessible	Accessible	MR
	• Gate width	Accessible	Accessible	MR
	• Width of internal road	NA	NA	NA
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	02	02	MR
	• Basements	NA	NA	NA
	b. Width of staircases			
	• Upper Floors	1.50m	1.20m & 1.70m	MR (being old case)
	• Basements	NA	NA	NA
	c. Protection of exits			
	• Fire check door	NA	NA	NA
	• Pressurization	NA	NA	NA
	d. No. of continuous staircases to terrace	NA	NA	NA
	e. Width of Corridor	NA	NA	NA
f. Door Size	01m	01m	MR	
3	Compartmentation.			
	• Fire check door	NA	NA	NA
	• Sealing of electrical shafts	NA	NA	NA
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4	Smoke Management System.			
	• Basements	NA	NA	NA
	• Upper floors	Required	Natural Ventilation	MR
5	Fire Extinguishers			
	• Total numbers	10nos	10nos	MR
	• Types	ABC	ABC	MR
	• ISI marking	ISI Marked	Yes	MR
6	First-Aid Hose Reels.			


		N/24	01	01	MR
	<ul style="list-style-type: none"> Total numbers on each floor Length of hose reel hose Nozzle diameter 	01	30m	30m	MR
		30m	5mm	5mm	MR
7	Automatic fire detection and alarming system.			NA	NA
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	NA	NA	NA	NA
8	MOEFA	NA	NA	NA	NA
9	Public Address System.	NA	NA	NA	NA
10	Automatic Sprinkler System.			NA	NA
	<ul style="list-style-type: none"> Basement Upper Floor Sprinkler above false ceiling 	NA	NA	NA	NA
11	Internal Hydrants			NA	NA
	<ul style="list-style-type: none"> Size of riser/down-comer Number of hydrants per floor Hose Box 	NA	NA	NA	NA
12	Yard Hydrants.			NA	NA
	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	NA	NA	NA	NA
13	Pumping Arrangements.				
	<ul style="list-style-type: none"> Ground Level <ul style="list-style-type: none"> Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual stopping Pump House Access Terrace level <ul style="list-style-type: none"> Discharge of pump Head of the pump Power Supply Auto Starting of pump 	N/A	N/A	N/A	N/A
		N/A	N/A	N/A	N/A
		N/A	N/A	N/A	N/A
		N/A	N/A	N/A	N/A
		N/A	N/A	N/A	N/A
		N/A	N/A	N/A	N/A
		N/A	N/A	N/A	N/A
		N/A	N/A	N/A	N/A
		N/A	N/A	N/A	N/A
		450 LPM	Provided	MR	MR
		40m	Provided	MR	MR
		Required	Provided	MR	MR
		Required	Provided	MR	MR
14	Captive Water Storage for fire fighting.				
	<ul style="list-style-type: none"> Underground tank capacity Draw-off connection Fire service inlet Access to tank Overhead Tank capacity 	NA	NA	NA	NA
		NA	NA	NA	NA
		NA	NA	NA	NA
		NA	NA	NA	NA
		10,000 LTR	NA	NA	NA
15	Exit Signage.	Required	Provided	MR	MR
16	Provision of Lifts.			MR	MR
	<ul style="list-style-type: none"> Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A	N/A
		N/A	N/A	N/A	N/A
		N/A	N/A	N/A	N/A
		N/A	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A	N/A
		N/A	N/A	N/A	N/A

N/25


18	Refuge Area.			
	➤ Total Area	N/A	N/A	N/A
19	➤ Location	N/A	N/A	N/A
	Fire Control Room			
	• Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel	N/A	N/A	N/A
	• PA System Panel	N/A	N/A	N/A
	• Batter backup	N/A	N/A	N/A
20	• Building Floor Plans	N/A	N/A	N/A
	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection.


Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part-4, it is recommended for renewal of fire safety certificate issued vide this department letter of even no. F6/DFS/MS/2020/WZ/27 dated: 27/01/2020.


 Signature of the Inspecting Officer
 Name :- C.L. Meena
 Designation:- ADO/RN



 Dy. CFO (WZ)



 22/9

DCFO/528-NW
 Dated 22/09/25



 Principal Director


 22/09/25


 24/9/2025


 ADO (RN)
 As approved, F.T. letter is put up for your signature please


 26/9/2025


 25/09/2025
 ADO (RN)