

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**

C-118  
T  
आजादी का  
अमृत महोत्सव


Dated: - 30/05/2025

F6/DFS/MS/GH/NDZ/2025/ 384

**FIRE SAFETY CERTIFICATE**

Certified that the **Sudershan Palace Guest House**, located at **8189/6, Multani Dhanda, Pahar Ganj, New Delhi-110055**, comprised of **Ground + 04 Upper Floors, ground floor (reception), 1<sup>st</sup> to 3<sup>rd</sup> floor (03 guest rooms at each floor) and 4<sup>th</sup> floor (not in use) (Total 09 guest rooms only)**, owned/occupier by **Sudershan Palace Guest House**, was issued Fire Safety Certificate by this department vide letter no. **F6/DFS/MS/GH/NDZ/2022/337** dated **11/07/2022**. The said premise was re-inspected by the officer concerned of this department on **21/05/2025** in the presence of **Sh. Satish Kumar Chawla (Partner)** and found that the said guest house building having **given an affidavit dated 28/12/2019 regarding not to use any floor above 3<sup>rd</sup> floor**, has deemed complied with the fire prevention and fire safety requirements in accordance with the Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises/building is fit for occupancy class **Residential, Sub Division A-1** as above **ground floor (reception) 1<sup>st</sup> to 3<sup>rd</sup> floor (03 guest rooms at each floor) Total 09 guest rooms upto 3<sup>rd</sup> floor only**, with effect from **30/05/2025** for a period of **three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010 printed below.

Issued on 30/05/2025 at New Delhi by

  
30/5/2025  
(Virendra Singh)  
Chief Fire Officer  
Delhi Fire Service  
9<sup>th</sup> 29/5

Copy to: -

1. The Commissioner, Municipal Corporation of Delhi, Civic Centre, Minto Road, New Delhi-110002:- in r/o computer id no. 2025043007586 dated 30/04/2025, also to ensure occupancy as detailed above and deviation, if any.
2. The Joint Commissioner of Police (Lic), 1<sup>st</sup> Floor, Licensing Unit, Police Station, Defence Colony, New Delhi
3. The Authorized Signatory, Sudershan Palace Guest House, 8189/6, Multani Dhanda, Pahar Ganj, New Delhi-110055.

**Conditions for the validity of fire safety certificate: -**

1. All the means of escape shall be kept free of all type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the firefighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
6. All comments / directions of licensing Department shall always be permitted and followed.
7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
9. Any flammable material for interior decoration is prohibited.

**INSPECTION REPORT**

1. Name & address of the building : **Sudarshan Palace Guest House**, located at **8189/6, Multani Dhanda, Pahar Ganj, New Delhi-110055**
2. Type of Occupancy : Residential Sub Division A-1,  
Ground + 04 Upper Floors (Total 09 Guest Rooms) ground floor (reception) 1<sup>st</sup> to 3rd floor (03 guest rooms at each floor) and 4<sup>th</sup> floor (not in use) an affidavit dated **28/12/2019** regarding not to use any floor above third floor
3. Type of Case : Renewal
4. Details of previous NOC : F6/DFS/MS/GH/NDZ/2022/337 dated 11/07/2022
5. Fire Safety directives Letter No. : N/A
6. Date of inspection : 21/05/2025
7. Name of the Inspecting Officer : Aman Kumar Lathar, ADO (JWP)
8. Name and designation of Officer from the building side : Sh. Satish Kumar Chawla (Partner)
9. Year of Construction : 1999
10. Applicant's online application no. : 2025043007586 dated 30/04/2025

S No	Minimum standards on fire prevention and fire safety U/R 33	Requirements Existing fire safety arrangements	Provided at site	Remarks MR/NMR
1.	Access of building	NA	06 m	NA
	• Road width	NA	NA	NA
	• Gate width	NA	NA	NA
	• Width of internal road	NA	NA	NA
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases	01 no.	Provided	MR
	• Upper floors	NA	NA	NA
	• Basements			
	b. Width of staircases	0.80 m	1.0 m	MR
	• Upper floors	NA	NA	NA
	• Basements			
	c. Protection of exits	NA	NA	NA
	• Fire check door	NA	NA	NA
	• Pressurization	NA	NA	NA
	d. No of continuous staircase to terrace	NA	NA	NA
	e. Width Of Corridor	1.0 m	Provided	MR
	f. Door Size			
3.	Compartmentation	NA	NA	NA
	• Fire check door	NA	NA	NA
	• Sealing of electrical shafts	NA	NA	NA
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4.	Smoke managements System	NA	NA	NA
	• Basements	Required	Natural	MR
	• Upper floors			
5.	Fire Extinguishers	08 nos.	Provided	MR
	• Total numbers	ABC & CO <sub>2</sub>	Provided	MR
	• Types	Required	Provided	MR
	• IS marking			

6.	First – Aid Hose Reels		Provided	MR
	• Total numbers on each floor	01 no.		MR
	• Length of hose reel hose	30 m	Provided	MR
	• Nozzle diameter	05 mm	Provided	MR
7.	Automatic fire detection and alarming system			
	• Type of detectors (CO Type)	Required	Provided	MR
	• Location of Main Panel	Ground Floor	Provided	MR
	• Location of Repeater Panel	NA	NA	NA
	• Alternate source of power	Required	Provided	MR
	• Hooters' Location	Each Floor	Provided	MR
8.	MOEFA	NA	NA	NA
9.	Public Address System	NA	Provided	NA
10.	Automatic Sprinkler System			
	• Basements	NA	NA	NA
	• Upper Floor	NA	NA	NA
	• Sprinkler above false ceiling	NA	NA	NA
11.	Internal Hydrants:			
	• Size of riser/down- comer	NA	NA	NA
	• Number of hydrants per floor	NA	NA	NA
	• Hose Box	NA	NA	NA
12.	Yard Hydrants			
	• Total number of hydrants	NA	NA	NA
	• Hose Box	NA	NA	NA
13.	Pumping Arrangements:			
	• Ground Level	NA	NA	NA
	• Discharge of main pump	NA	NA	NA
	➤ Head of main pump	NA	NA	NA
	➤ Number of main pumps	NA	NA	NA
	➤ Jockey pump out put	NA	NA	NA
	➤ Jockey pump head	NA	NA	NA
	➤ Standby Pump out put	NA	NA	NA
	➤ Standby Pump Head	NA	NA	NA
	➤ Auto Staring/Manual stopping	NA	NA	NA
	➤ Pump House Access	NA	NA	NA
	• Terrace level			
	➤ Discharge of pump	225 lpm	Provided	MR
	➤ Head of the pump	18 m	Provided	MR
	➤ Power supply	Required	Provided	MR
	➤ Auto starting of pump	Required	Provided	MR
14.	Captive water Storage for fire fighting:			
	• Under ground tank capacity	NA	NA	NA
	➤ Draw off connection	NA	NA	NA
	➤ Fire service inlet	NA	NA	NA
	➤ Access to tank	NA	NA	NA
	• Overhead Tank capacity	2500 ltrs.	Provided	MR
15	Exit Signage	Required	Provided	MR
16.	Provision of Lifts			
	➤ Pressurization of Lift Shaft	NA	NA	NA
	➤ Pressurization of lift lobby	NA	NA	NA
	➤ Communication in lift Car	NA	NA	NA
	➤ Fireman's Grounding Switch	NA	NA	NA
	➤ Lift Signage	NA	NA	NA
17.	Standby power supply	Required	Provided	MR

18.	Refuge Area	NA	NA	NA
	<ul style="list-style-type: none"> <li>➤ Total area</li> <li>➤ Location</li> </ul>	NA	NA	NA
19.	Fire control room	NA	NA	NA
	➤ Detector system panel	NA	NA	NA
	➤ Flow Switch Panel	NA	NA	NA
	➤ PA System Panel	NA	NA	NA
	➤ Battery backup	NA	NA	NA
20.	Building Floor Plans	NA	NA	NA
	Special Fire Protection Systems for Protection of special Risks, if any;	NA	NA	NA

The fire protection systems provided in the building were checked and found functional at the time of inspection. Shortcomings issued vide letter no. F.6/DFS/MS/NDZ/GH/2025/151 dated 03/04/2025 found rectified.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2022/337 dated 11/07/2022, renewal under rule 37 of the Delhi Fire Service Rule 2010, is recommended.

Accordingly, DFA is put up for approval & signature please.

*Aman Kumar Lathar*  
23/05/25  
Aman Kumar Lathar  
ADO (JWP)

*DO (CD)*

*26/5/25*

*C.F.O.*

*26/05/25*

*C.F.O.*

*28/5/2025*

*DO*

*DO (CD)*

*29/5*

*As approved*

As approved, F.T letter is put up for signature please

*C.F.O.*  
*30/5/2025*

*MS Cell*  
*uploaded*  
*26/5/25*  
*29/5/25*  
*Khatri*