

c-61

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001


No.F.6/DFS/MS/School/2026/North-Zone/148

Dated: 14/09/2026

FIRE SAFETY CERTIFICATE

Certified that the **Vanasthali Public School** located at **Ghevra – Nizampur Road, Delhi – 110081** comprised of Ground + 02 Upper floor, owned/occupied by **Vanasthali Public School** was issued FSC by this department vide letter No. F.6/DFS/MS/2023/School/WZ/286 Dated 28.04.2023. The building was re-inspected by the officer concerned of this department on 19/08/2026 in the presence of Smt. Sangeeta Sharma (Principal), and observed that all the fire prevention and fire safety arrangements as provided in the building found in good working condition. The premises have deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and that the building is fit for occupancy **Group B "Educational (School),"** with effect from 14/09/2026 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 14/09/2026 at New Delhi by.


(Dr. S. K. Tomar)
Chief Fire Officer
Delhi Fire Service


Copy to: -

1. Smt. Sangeeta Sharma (Principal), Vanasthali Public School located at Ghevra – Nizampur Road, Delhi – 110081. (Email -vanasthalinizampur@gmail.com)
2. The Director of Education, MCD, Dr. SPM Civic Centre, JLN Marg, New Delhi-110002.

Condition for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
4. All the staff members must know the correct method of operation of firefighting system.
5. The trained firefighting staff should be available at the site round the clock.
6. Any deviation with regard to the construction etc. shall be verified by the concerned building sanctioning authority.
7. The owner/ occupier shall submit a declaration **every year** in **Form 'K'** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
8. This fire safety certificate may not in any way be treated as regularization of unauthorized construction, if any. Basement shall be used as per BBL concerned.
9. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in **Form 'J'** [sub rule (1) of rule 37] along with a copy of this Certificate, **six months** prior to its expiry."

N/36
INSPECTION REPORT

1.	Name & address of the building	Vanasthali Public School located at Ghevra - Nizampur Road, Delhi - 110081		
2.	Building comprised of	Ground + 02 upper floor		
3.	Type of occupancy	Educational, (Group B)		
4.	Type of case	Addition/Alteration (Lift installed)		
5.	Details of previous FSC No.	F.6/DFS/MS/2023/School/WZ/286 dated 28/04/2023		
6.	Fire safety directives No.-	NBC Part - IV		
7.	Date of inspection: -	19/08/2026		
8.	Name of the inspecting officer:	Nitin Lohchab, ADO (BW)		
9.	Name & designation of officer from the building side: -	Smt. Sangeeta Sharma (Principal)		
10.	Year of construction: -	2000 & 2017		
11.	Applicant's letter No: -	e-mail dated 18/08/2026		
S. No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement as per NBC	Provided at site	Remarks MR/NMR
1.	Access to Building			
	• Road width	06 mtrs.	12 mtrs.	MR
	• Gate width	4.5 m	Provided	MR
	• Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper floors	02 Nos.	03 nos.	MR
	• Basements	N/A	N/A	N/A
	b. Width of staircase			
	• Upper floors	1.50 m X 02 nos.	1.40 m, 1.50 m & 1.80 m	MR
	• Basements	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	NA	NA	NA
	• Pressurization	NA	NA	NA
	d. No. of continuous staircase to terrace	01 Nos.	03 Nos.	MR
	e. Width of corridor	1.50 m	2.30 m	MR
	f. Door size	01 m	01 m	MR
3.	Compartmentation			
	• Fire check door	NA	NA	NA
	• Sealing of electrical shafts	NA	NA	NA
	• Fire rating of shaft door	NA	NA	NA
	• Water curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
	• Basements	NA	NA	NA
	• Upper floors	Required	Provided (Natural Ventilation)	MR
5.	Fire Extinguishers			
	• Total numbers	12 nos.	12 nos.	MR
	• Types	ABC/Co2	ABC/Co2	MR
	• ISI marking	ISI Marked	Provided	MR

A A

6.	First-Aid Hose Reel			
	• Total number of each floor	02 nos.	02 nos.	MR
	• Length of hose reel hose	30 mtr.	30 mtr.	MR
	• Nozzle diameter	5 mm	5 mm	MR
7.	Automatic Fire Detection & Alarming System.			
	• Type of detectors	NA	NA	NA
	• Location of main panel	NA	NA	NA
	• Location of repeater panel	NA	NA	NA
	• Alternate source of power	NA	NA	NA
	• Hooter's Location	NA	NA	NA
8.	MOEFA	NA	NA	NA
9.	Public Address System	NA	NA	NA
10.	Automatic Sprinkler System			
	• Basement	N/A	N/A	N/A
	• Upper floors	N/A	N/A	N/A
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	• Size of riser/ down-comer	N/A	N/A	N/A
	• Number of hydrants per floor	N/A	N/A	N/A
	• Hose box per floor	N/A	N/A	N/A
12.	Yard Hydrants			
	• Total number of hydrants	N/A	N/A	N/A
	• Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	Ground level			
	• Discharge of main pump	N/A	N/A	N/A
	• Head of main pump	N/A	N/A	N/A
	• Number of main pumps	N/A	N/A	N/A
	• Jockey pump out put	N/A	N/A	N/A
	• Jockey pump head	N/A	N/A	N/A
	• Stand by pump output	N/A	N/A	N/A
	• Stand by pump head	N/A	N/A	N/A
	• Auto starting/ Manual stopping	N/A	N/A	N/A
	Terrace level			
	• Discharge of pump	450 lpm	Provided	MR
	• Head of pump	40 M	Provided	MR
	• Power supply	Required	Provided	MR
	• Auto starting of pump	Required	Provided	MR
14.	Captive Water Storage for Fire Fighting			
	• Underground tank capacity	N/A	N/A	N/A
	• Draw-off connection	N/A	N/A	N/A
	• Fire service inlet	N/A	N/A	N/A
	• Access to tank	NA	NA	NA
	• Overhead tank capacity	10,000 ltrs	10,000 ltrs	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	• Pressurization of lift shaft	N/A	N/A	N/A
	• Pressurization of lift lobby	N/A	N/A	N/A
	• Communication in lift car	Required	Provided	MR
	• Fireman's switch	Required	Provided	MR
	• Lift signage	Required	Provided	MR
17.	Stand by Power Supply	NA	NA	NA

18.	Refuge Area			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19.	Fire Control Room			
	• Detector system panel	N/A	N/A	N/A
	• Flow switch panel	N/A	N/A	N/A
	• PA system panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:	NA	NA	NA

The fire protection systems provided in the building/premises were checked, tested at random and found functional at the time of inspection. The shortcomings communicated by this department vide letter No. F.6/DFS/MS/School/2026/601 dated 30/06/2026 have been complied.

Keeping in view of the substantial compliance of the minimum fire safety standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire safety certificate (FSC) to said school.

Accordingly, DFA is put up for approval & signature please.

Nitin Lohchab
Nitin Lohchab
ADO (BW)

~~DO/Outer North~~

for Approval Please.

~~CFO (North)~~

[Signature]
20/08/2026

[Signature]
20/8/26

~~Principal Director~~

cfo to issue. *[Signature]*

~~CFO (H)~~

[Signature]
20/9/26

~~ADO/BW~~

F.T letter is put up for your perusal & signature please.

~~CFO (Ctn)~~

Pl. put up corrected F.T.

[Signature]
20/9/26

Nitin Lohchab
20/9/26

~~ADO (BW)~~